TO:	API number: 15-00403072-0000
STATE CORPORATION COMMISSION	/
CONSERVATION DIVISION - PLUGGING	NE NW NE /4 SEC. 12 , 16 S , 12 W
130 S. MARKET, ROOM #2078	4950 feet from S section line
WICHITA, KANSAS 67202	1650 feet from E section line
Operator license#_6357	Lease_Woydzick well #_2
Operator: Webco Oil Company	County Barton
	Well total depth 3301 feet Conductor Pipe: 0 inch 0 0 feet
Address: 1303 Baker	Well total depth 3301 feet
Great Bend, Kansas 67530	Conductor Pipe: 0 inch @ 0 feet
	Surface pipe 8 5/8 Inch @ 773 feet
Aband. oil well <u>X</u> , Gas well, Inpu	<del></del> ·
Plugging contractor: <u>Mike's Testing &amp; Salvage, Inc.</u> License# 31529	
Prugging Contractor: <u>Mike-s Testing &amp;</u>	salvage, inc. License#_31529
Address: P.O. Box 209 - Chase, Kansas 67524	
Company to plug at: Hour: 10:00A.M. Day: 9 Month: June Year: 95	
Diverging proposal received from Wiles Voles	
Plugging proposal received from: Mike Kelso	
Company: Mike's Testing & Salvage, Inc. Phone: 316-938-2943	
Were: Order 225 sxs. 60/40 posmix - 10% gel and hulls.	
Plug while pulling casing.	DECEMED.
	STATE CORPORATION COMMISSION
	<u>JUN 1 6 1995</u>
	<del>-</del>
Plugging Proposal Received by: Herb Deines	
Plugging Proposal Received by: <u>Herb Deines</u> Plugging operations attended by agent? All[X], Part[ Cliver None[America]	
Completed: Hour: 1:00P.M., Day: 9, Month: June, Year: 95	
Actual plugging report: 8 5/8" to 773'. 5 1/2" to 3298'. Sanded back to	
2850' and spotted 5 sxs. cement with	dumn bailer During stratch test to
determine cut off point, colar stripped and parted casing at 718. Attempts	
to screw back onto casing unsuccessful	1 Mived and numbed 130 sys coment
with 300# hulls. Pulled casing and tied	onto surface pipe. Mixed and pumped
60 sxs. cement with 200# hulls. Calc	ulated cement coverage from 718! to
2025' in casing annulus. Pumped cemen	t until well locked up. Max. P.S.T.
800#. S.I.P. 800#. Confirmed damage to	hottom colar which had impact damage
to prevent screwing back into casing.	DOUGOM COTAL MATON Mad Impact demage
TO PERSONAL DESCRIPTION ORDINGS	
Remarks:	
Condition of casing(in hole):GOOD X	BAD Anhy.plug:YES_ X NO
Bottom plug(in place):YES X ,CALC	,NO Dakota plug:YES_X ,NO
Plugged through TUBING, CASING	X . Elevation: 1880 GL
<pre>I did[X ] / did not[ ] observe the pl</pre>	lugging.
NYD-ICFD	(agent)
HAAIAFA	Form CP-2/3
1 0 1 111	FOI II CP-2/3