

R

KANSAS  
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:  
Jewel M. Ogden, Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

File No. \_\_\_\_\_ County: Trego

Location: NW NW SW Sec. 6 Twp. 11 Rge. 24 (E) (W) \_\_\_\_\_

Name of Field: \_\_\_\_\_ Total Depth: 4020'

I have this date completed supervision of plugging of:

Lease Name: Burg Well No. 1

Operator's Full Name: Murfin-Rains & Williamson

Complete Address: 1 617 Union Center, Wichita, Kansas

Plugging Contractor: Same

Address: \_\_\_\_\_ License No. \_\_\_\_\_

Oil Well \_\_\_\_\_ Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well \_\_\_\_\_ D & A

Other well as hereafter indicated: Dry Hole

Was any delay in plugging operations caused by Conservation Division Agent? Yes \_\_\_\_\_ No

If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 9am Day 15 Month May Year 1958

The above well was plugged as follows:

TD.-4020, 8 5/8 set at 208'  
Gunned Pitts Cir. hole with heavy mud, set cementing plug at 540' and dis-  
placed 20 sax cement thru drill pipe, heavy mud to 180' set cementing plug  
and displaced 20 sax cement thru drill pipe, heavy mud to 40' set and tied  
cementing plug in place, and top with 10 sax cement to bottom of cellar.

Signed: Gilbert P. Leiker  
Conservation Division Agent

Reviewed: J. Lewis Brock  
Field Supervisor

Remarks:

PLUGGING  
FILE SEC. 6 T. 11 R. 24W  
BOOK PAGE 101 LINE 27