

DISTRICT CONSERVATION AGENT'S REPORT

R

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION SW-SW-NW

SEC 33 TWP 21 RGE. 14W

Dry Hole X Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Cox

Operator Buick Bldg. inetal. Address P.O. Box 331 St. John, Kans.

Field _____ County Stafford

Total Depth 3892 Feet.

Plugging Contractor Buick Bldg. inc.

Plugging Contractor's License No. _____

Address Box 331 St. John Kansas

(Describe Briefly the manner in which the well was plugged)

*Surf Pipe 8 3/8 @ 283 cu. ft.
Plugged with hole full of Shell mud to
2 1/2 feet and 3/4 cu. ft. Halls and Plug sand
20 cu. ft. Cement through Buick Pipe and
and Shell mud to 20 feet and 3/4 cu. ft.
Halls and Plug and 5 cu. ft. Cement.
To base of the cell at 4 PM*

R. M. Brundage
District Conservation Agent

RECEIVED
STATE CORPORATION COMMISSION
Date Feb 27 1957

FFB

CONSERVATION DIVISION
Wichita, Kansas

2-28-1957

PLUGGING
FILE SEC. 33 T. 21 R. 14W
BOOK PAGE 144 LINE 18