

B

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. 70-40

LOCATION NE-NE-NW

SEC. 16 TWP. 21 RGE. 7W

Dry Hole _____ Abandoned Oil Well Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 7 Lease Patton "F"

Operator Lawrence Supply Co. Address 90 West Supply Co Inc Chase, Kansas

Field ✓ County Rice

Total Depth 3387 Feet.

Plugging Contractor West Supply Co Inc

Plugging Contractor's License No. 14

Address Chase, Kansas

(Describe briefly the manner in which the well was plugged)

Sand to 3380', 6 SW cement at 3380', hole muddied, hole made solid at 150', 2.5 SW cement at 150', mud to 25', bridge, 5 SW cement at top.

6-25-56

LIVE
CORPORATION COMMISSION

JUN 25 1956

Paul Dunbar
District Conservation Agent

Date 6-23-56

PLUGGING
FILE SEC. 16 T. 21 R. 7W
BOOK PAGE 70 L. E. 40

CONSERVATION DIVISION
Wichita, Kansas