

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission  
Conservation Division  
211 North Broadway  
Wichita, Kansas

FILE NO. ✓

LOCATION 7N-7W-5E

SEC. 13 TWP 21 RGE. 7W

Dry Hole ✓ Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have this date completed supervision of plugging of:

Well No. 1 Lease De Steen

Operator The Cherry Dalg Co. Inc. Address 102 Ins. Bldg Wichita Kans

Field \_\_\_\_\_ County Rice

Total Depth 3480 Feet.

Plugging Contractor Operator

Plugging Contractor's License No. ✓

Address ✓

(Describe Briefly the manner in which the well was plugged)

Gunned pits and circulated, hole made solid at 2.5, 15 1/2 cement then 7 joints drill pipe, mud to 2.5, bridge, 5 1/2 cement at top.

Paul Danke  
District Conservation Agent

Date 10-22-1957

RECEIVED  
OCT 23 1957  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

PLUGGING  
FILE SEC. 13 T. 21 R. 7W  
BOOK PAGE 36 LINE 11