

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission  
Conservation Division  
211 North Broadway  
Wichita, Kansas

FILE NO. 41-11

LOCATION SW. SW. SE

SEC. 23 TWP. 18 RGE. 16 W.

Dry Hole \_\_\_\_\_ Abandoned Oil Well ✓ Abandoned Gas Well \_\_\_\_\_

I have this date completed supervision of plugging of:

Well No. 2 Lease H.R. Woodward

Operator Dumas Mas Oil Co Address 32 Church street  
Waynesburg Pennsylvania

Field \_\_\_\_\_ County Rush

Total Depth 35-60 Feet.

Plugging Contractor R & S Pipe Pulling Co.

Plugging Contractor's License No. 1

Address Box 192 Ellinwood Kansas  
(Describe Briefly the manner in which the well was plugged)

Surf Pipe 13 1/2 @ 210 e.w. 525 sq cent.  
10 in @ 975 e.w. 528 sq cent.  
7 in @ 3523 sq. 528 sq cent.  
P.B. to 3.449 and top Reef @ 3.246  
Sand to 3.235 and 7 sq. cent. Pull 7 in  
fill hole with heavy mud and Rock B. to 375  
and 25 sq. cent. and mud & 16 to 35 & 10 sq.  
of cent. to base of cellar R.M. Brundage

District Conservation Agent

Date Aug. 5-1957

PLUGGING  
FILE SEC. 23 T. 18 R. 16 W.  
BOOK PAGE 41 LINE 11

FILED  
STATE CORPORATION COMMISSION  
SEP 6 1957  
DIVISION

9-6-57