

KCC OIL/GAS REGULATORY OFFICE

15.083.21471.0000

Date 11-19-01

- New Situation
- Response to Request
- Follow-up

Operator FALCON Exp., Inc # 9431

Address 155 N. MARICET Ste 1020

Location C E E NE, Sec 2, T 21 S, R 23 W

Wichita, Ks. 67202

Lease WHITLEY Well # 1-2

Phone No.

County HODGEMAN

Oper. 316-262-1378 Other \_\_\_\_\_

Reason for Investigation: ACT II Completion

Problem: none

RECEIVED

NOV 21 2001

KCC WICHITA

Person(s) Contacted: \_\_\_\_\_

Findings: 1600 HAS START ACT II Completion. \* Part collar set @ 1481.7'

open tool and established immediate circulation.

only 1 1/2 pumped 225 SACKS 60/40 Perm, 6% gel,

1/4" FLOW SEAL. Good labors throughout job.

Job completed @ 18:00 hrs.

photos taken: \_\_\_\_\_

Action/Recommendations: none / ACT II completed.

- Lease Inspection
- Complaint
- Field Report

By Steve Kliment

**LEASE INSPECTION**

- YES NONE COMMENTS
- I.D. Sign  [ ]
  - Tank Battery  [ ]; Condition: good  [ ] questionable  [ ] overflowing  [ ]
  - Pits, tank battery  [ ]; Fluid depth \_\_\_\_\_ ft.; approx. size \_\_\_\_\_ ft x \_\_\_\_\_ ft
  - Pit, injection site  [ ]; Fluid depth \_\_\_\_\_ ft.; approx. size \_\_\_\_\_ ft x \_\_\_\_\_ ft
  - Gas venting  [ ]
  - Oil spill evidence  [ ]
  - Saltwater evidence  [ ]; Surface flow \_\_\_\_\_; seepage \_\_\_\_\_
  - Saltwater pipelines  [ ]; Seepage visible Yes/No; tested for leaks Yes/No
  - Flowing holes  [ ]
  - Abandoned wells  [ ]
  - TA wells  [ ]; Potential poll. Prob. \_\_\_\_\_; currently producing \_\_\_\_\_
  - SWD/ER Injection well  [ ]; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi
  - SWD/ER Injection well  [ ]; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi
  - SWD/ER Injection well  [ ]; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi
  - SWD/ER Injection well  [ ]; Permit # \_\_\_\_\_ Pressure-actual \_\_\_\_\_ psi, Authorized \_\_\_\_\_ psi
  - Monitoring records  [ ]
  - Gauge connections  [ ]; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_
  - Gauge connections  [ ]; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_
  - Gauge connections  [ ]; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_
  - Gauge connections  [ ]; tubing \_\_\_\_\_; T/C annulus \_\_\_\_\_; C/SP annulus \_\_\_\_\_

Lease cleanliness: Very good \_\_\_\_\_ satisfactory \_\_\_\_\_ poor \_\_\_\_\_ very bad \_\_\_\_\_

Water samples taken \_\_\_\_\_

Reports prepared \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

+	+	+	+
+	+	+	+
+	+	+	+
+	+	+	+