KCC OIL/GAS REGULATORY OFFICES

Date: <u>08/24/17</u>	District: _1	Case #:				
4 ³	New Situation	Lease Inspection				
	Response to Request	Complaint				
	Follow-Up	Field Report				
Operator License No: <u>NA/ Spud date 1/03/62</u>	API Well Number: 15-00	07-00093-00-00				
Op Name: Crescent Oil & Gas Corp	Spot: <u>SWSE</u>	Sec <u>36</u> Twp <u>30</u> S Rng <u>15</u> E / W				
Address 1:	638	Feet from N/ S Line of Section				
Address 2:	1985	Feet from Feet from V Line of Section				
City:		Long: <u>98.90929</u> Date: <u>1/24/17</u>				
State: Zip Code:	Lease Name: <u>Hoagland</u>	Well #: _1				
Operator Phone #:	County: Rarber					
Reason for Investigation:						
To dig up AX (status) well						
Problem:						
No plugging report on well w/ a completion date of 1/16/62. Loggers TD at 4655.						
Persons Contacted:						
Scott Alberg, Patrick Shields, and Michele	Pennington					
Book, aborg, Faurok ornolas, and Micholo	ommigton.					
Findings:						
10:00 AM Had Pratt Oil Field Service, Inc. on site with Backhoe. Dug out well and found surface pipe standing full with						
cement. Covered well back off and leveled back off.						
Action/Recommendations: Fol	low Up Required Yes N	o Date:				
Well should be shown as P&A on completion		_				
Case closed	on date of 17 to/ 1902					
Verification Sources:		Photos Taken: 1				
✓ RBDMS KGS	TA Program					
T-I Database	Courthouse By: Ste	ve Pfeifer				
Other: Uncover well & inspect.						
Retain 1 Copy District Office						

Send 1 Copy to Conservation Division

Form:

AX Status Review - Field Report

RBDIVIS Well I	<u>nformation</u>						
Well Name	e: HOAGLAND		API: 15-007-00093-00-00				
		_					
<u>Count</u>	nty: BARBER		<u>District</u>	<u>::</u>	1		
Quarter Calls Section		Section	Township	Range	RangeDir		
SWSE 36		36	30	15	W		
Latitude:	37.385731	Footage	N/S	Footage	E/W		
Longitude:	-98.908943	660	S	1980	E		
Agent Findings Agent: Steve Pfeifer Inspection Date: 8/24/17							
Well Status:	Inactive	Producing	Active Inj/Disp	Other	Not Found		
(Check One)				×	-		
Comments:	Had Pratt Oil Field Service, Inc. on site with Backhoe. Dug out well and found surface pipe standing full with cement. Covered well back off and leveled back off. Well should be shown as P&A on completion date of 1/16/1962 Case closed						
<u>Contacts:</u>		····		Photo Taken	Y		
Information L	<u>Jpdate</u>						
<u>Latitude</u> :	37.38570	Footage	N/S	Footage	E/W		
Longitude:	98.90929	638	S	1985	E		
Potential Responsible Party:			<u>License #:</u>				

AX Status Review - Field Report

RBDMS Well Information HOAGLAND Well Name: 15-007-00093-00-00 API: BARBER 1 County: District: **Quarter Calls** Section **Township** Range RangeDir **SWSE** 36 30 15 W Latitude: 37.385731 **Footage** N/S E/W Footage S Longitude: -98.908943 660 1980 E **Agent Findings** Inspection Date: 1/24/2017 Agent: Steve Pfeifer Well Status: **Inactive Producing** Active Inj/Disp Other Not Found Х (Check One) Comments: Found what appeared to be old location in rough pasture. Using metal detector I picked up very strong single at the base of small cedar and the GPS coordinates below. Augured a hole at this location and encountered either cement or gray shale, and water at approx 3'. Would have to be dug up to verify. Legacy Operator was Crescent Oil & Gas Corp. Spud date 1/03/1962 / TD reached on 1/16/1962. Well was a DH approved for plugging. No plugging report to be found. Last recorded Lease was Fred Hambright to Vess Oil Corp. on Mar. 29/2006, Bk 308, Pg 158,160,162. Vess currently operates a well (Hoagland 1-36) in the NWSW/4 & drilled a DH (Hoagland B 1-36) in the NWSE/4 P&A in 8/18/2006. See attached landowner information. Contacts: Scott Alberg Register of Deeds & Appraisers office. Photo Taken? 0 Information Update Latitude: 37.38570 N/S E/W **Footage Footage** Longitude: 98.90929 638 fsl 1985 fel Potential Responsible Party: License #: