

AX Status Review - Field Report

RBDMS Well Information

<u>Well Name:</u>	WIELAND 6	<u>API:</u>	15-063-21245-00-00
<u>County:</u>	GOVE	<u>District:</u>	4

Quarter Calls	Section	Township	Range	RangeDir
SWSWSE	8	11	31	W
<u>Latitude:</u>	39.105831	Footage	N/S	Footage
<u>Longitude:</u>	-100.783302	330	S	2310
				E/W
				E

Agent Findings

<u>Agent:</u>	MARVIN MILLS	<u>Inspection Date:</u>	12-21-2016
---------------	--------------	-------------------------	------------

<u>Well Status:</u>	Inactive	Producing	Active Inj/Disp	Other	Not Found
(Check One)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments: WELL WAS A ROTATARY DNA IS PLUGGED DRY HOLE NEVER SET PIPE AS PER WALTERS LIBRARY CARD PLUGGED IN JAN 9-1989

Contacts:

Photo Taken?

Information Update

<u>Latitude:</u>		Footage	N/S	Footage	E/W
<u>Longitude:</u>					

<u>Potential Responsible Party:</u>	<u>License #:</u>