

AX Status Review - Field Report

RBDMS Well Information

<u>Well Name:</u> JACKA 3	<u>API:</u> 15-063-30080-00-00
<u>County:</u> GOVE	<u>District:</u> 4

Quarter Calls	Section	Township	Range	RangeDir
SENE	8	15	26	W

<u>Latitude:</u>	38.757809	<u>Footage</u>	N/S	<u>Footage</u>	E/W
<u>Longitude:</u>	-100.228569	3300	S	660	E

Agent Findings

<u>Agent:</u> MARVIN MILLS	<u>Inspection Date:</u> 12-21-2016
--	--

<u>Well Status:</u>	Inactive	Producing	Active Inj/Disp	Other	Not Found
(Check One)					

Comments: WELL IS PLUGGED REPORT IN RBDMS PLUGGED 2-4-1966
MARV MILLS

Contacts:

Photo Taken? NO

Information Update

<u>Latitude:</u>	38.76502	<u>Footage</u>	N/S	<u>Footage</u>	E/W
<u>Longitude:</u>	100.22880				

<u>Potential Responsible Party:</u>	<u>License #:</u>