AX Status Review - Field Report

VODIAIO M.EII IIII	<u>Ormacion</u>				
Well Name:	COBERLY 27-4		API	API: 15-063-20692-00-0	
<u>County:</u>	GOVE		<u>District:</u>		4
Quarter Calls		Section	Township	Range	RangeDir
NWNW		27	15	28	W
Latitude:	38.7267	Footage	N/S	Footage	E/W
Longitude:	-100.427727	4605	S	4494	E
Agent Findings Agent: MARVIN MILLS			Inspection Date: 12-21-2016		
Well Status:	Inactive	Producing	Active Inj/Disp	Other	Not Found
(Check One)					
L	IBRARY CARD	Y HOLE ROTA	RTY PLUG DONE	- SEPT 9 1983 P	PER WALTERS
<u>Contacts:</u>				Photo Taken?	
Information Update					
<u>Latitude:</u>		Footage	N/S	Footage	E/W
Longitude:					
Potential Responsible Party:				<u>License #:</u>	