9-21 API Number: 15-009-23,549.000 TO: STATE CORPORATION COMMISSION NW NE NW /4 SEC. 17 , 20 S, 13 W CONSERVATION DIVISION - PLUGGING 4950 ___ feet from S section line 130 SOUTH MARKET, SUITE 2078 3630 feet from E section line WICHITA, KANSAS 67202 Lease: _____Hart _____Well#__2___ Operator license#_31410 116,35 County: Barton Operator: Barco, Inc.
 Well total depth
 3580
 feet

 Conductor Pipe:
 0 inch @
 0 feet
Address: P.O. Box 1557 Great Bend, Kansas 67530 Surface pipe 8 5/8 Inch @____322 feet Aband. oil well_X Gas well____, Input well___, SWD___, D & A____ Plugging contractor: Mike's Testing and Salvage License# -Address: Company to plug at: Hour: 1:00 P.M. Day: 21 Month: September Year: 1998 Plugging proposal received from: Mike Kelso Company: Mike's Testing and Salvage Phone: Were: Same as below. Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X], Part[], None[] Completed: Hour: 5:00 P.M., Day:21, Month: September, Year: 1998 Actual plugging report: Well was flowing back. Set CIBP at 3200'. Shot off pipe at 1800'. Pulled to 1575' and pumped 110 sxs 60/40 pozmix - 10% gel cement with 300# hulls. Pulled to 800' and pumped 35 sxs with 100# hulls. Pulled to 375' and pumped 35 sxs with 100# hulls. Pulled to 150' and circulated with 45 sxs. scale Remarks: Allied Cementing. Casing had holes and heavy states in first 500'. Condition of casing(in hole): GOOD_____BAD___X____ Anhy.plug: YES__X__ NO___ Bottom plug(in place): YES_X_, CALC____, NO____ Dakota plug: YES X , NO NO Plugged through TUBING_____, CASING__X___. Elevation:_____GL] observe the plugging. Case Monie I did[x] / did not[(agent) Form CP-2/3