TO: TO: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	API number: 15-009-24  NW SE SE /4 SEC. 34  990 feet from 990 feet from	4 , 20 S, 14 W S section line
Operator license# <u>6627</u>	Lease <u>Marmie</u>	well #_1
Operator: Prospect Oil & Gas Co.	County Barton	
Address: P.O. Box 837 Russell, Kansas 67665	Well total depth 3 Conductor Pipe: 0 Surface pipe 8 5/8	inch 0 feet
Aband. oil well, Gas well, Inp	ut well, SWD	, D & A <u>X</u>
Plugging contractor: Allen Drilling		License# <u>5418</u>
Address: <u>1105 Walnut, P.O. Box 1389, G</u>	reat Bend, Kansas 6	7530
Company to plug at: Hour: P.M. Day:	9 Month: July	Year: <u>92</u>
Plugging proposal received from: Mike	Kern	
Company: Allen Drilling	Phone: 913-4	83-6266
problems. Mud condition 48 vis 9.9 60/40 pozmix - 6% g Spot with dril between all plugs. 25 sx. @ 3480' - 2 10 sx. @ 40' - 15 sx. in Rathole (circ	l stem. Circulate ho 5 sx. @ 800' - 100 s	le. Heavy mud
Plugging Proposal Received by: <u>Mari</u> Plugging operations attended by agent? Completed: Hour: 6:45P.M., Day: 9 , Mo	All[ ], Part[	
Actual plugging report: Allen Drillin 6% gel. Circulated hole. Spotted and with heavy mud between all plugs.  1st. plug @ 3480' w/25 sx. cement.  2nd. plug @ 800' w/25 sx. cement.  3rd. plug @ 450' w/100 sx. cement.  4th. plug @ 40' w/10 sx. cement.  15 sx. in Rathole. (Circulate)	displaced cement three	ough drill stem
Remarks: Cemented by Allied Cemen Condition of casing (in hole):GOOD B Bottom plug (in place):YES X , CALC Plugged through TUBING , CASING X  I did O Condition of casing in hole):GOOD B  ATE AUG 0 7 1992  AV. NO. 35886  7-9 OCI 2 8 1992	ADAnhy.plug:YES ,NODakota plug Elevation: 190	g: YESIAX: NO CEIVED 00 GLODORATION COMMISSION