

DISTRICT CONSERVATION AGENT'S REPORT

R

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION SW-SW-NW

SEC. 21 TWP. 20 RGE. 12 W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Hulme

Operator Herdon Drly Co. Address 423 Mayo Bldg, Tulsa Okla.

Field _____ County BARTON

Total Depth 3513 Feet.

Plugging Contractor Herdon Drly Co.

Plugging Contractor's License No. _____

Address 423 Mayo Bldg, Tulsa, Okla.

(Describe briefly the manner in which the well was plugged)

Surface Pipe 8 5/8" (4) 277' C.W.B. Filled hole with
heavy mud. Set 3' 5x of tulls and H.O.W.C.O.
Plug at 270' mixed and poured in thru drill
pipe. Mud to 40' tulls, Plug, and 10' 5x of
mixed Cen. to surface.

12-23-53

PLUGGING
FILE SEC 21 T 20 R 12W
BOOK PAGE 3 LINE 6

Warren H. Horner
District Conservation Agent

Date 12-19-53