STATE OF KANSAS STATE CORPORATION COMMISSION

Form CP-4

Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Conservation Division

ه درستي

WELL PLUGGING RECORD

State Corporation Commission 212 No. Market	Barton	Count	v. Sec. 16	Twp.20 Rge	$(E)_{-}$	(W)
Wichita, Kansas NORTH	Location as "NE/CNW	SW4" or footage fro	m lines	SE SE SE		
	¬ Leace Owner	Location as "NE/CNW%SW%" or footage from lines SE SE SE Lease Owner Tomlinson Kathol				
	Lease Name		Scheufler		_ Well No	5
Lease Name Scheufler Well No Office Address Wichita, Kansas						
	Character of Well (completed as Oil, Gas or Dry Hole)					
1 ! !	Date well completed					
	Application for plugging					_19
	Application for plugging	approved	67			_19
	Plugging commenced Plugging completed	1/9/	67			
lii	Plugging completed		- f1i			
	Reason for abandonmen	t or wen or producin	g tomation			
	If a producing well is a	bandoned, date of la	ast production			19
	Was permission obtaine					
Locate well correctly on above Section Plat	menced?		yes			
Name of Conservation Agent who supe	rvised plugging of this well	1	ruan .			-,
Producing formation	Depth to	top Botton	n	. Total Depth of	$w_{\rm ell}$ 330.	5½ Feet
Show depth and thickness of all water,	oil and gas formations.					
OIL, CAS OR WATER RECORD	ne				CASING REC	CORD
·				-	1	
FORMATION (/)	RE LEGICIAN VE DER	DM TO	SIZE	PUT IN	PULLED (
11.11	CHRPARATION COMPARSSIDE	·	8 5/8	324	none	
			4 1/2	32 93	1596	<u> </u>
	13N 24 1967		 		+	
				-	+	
· 16.2	ASERVATION DIVISION		 			
	Monno, Kanson		 			
					-	
parted pig down the l Shot pipe Lost 1200 shot pipe 420 casing floor, los 25 sacks r	f cement. Cleaned pe, pulled 6 joints noie, got hole of 4 at 2208, 2000, 1 wire line in hole at 1702, 1594, was. Finished public ded rack, bailed hourdcement. Mudded cement. Tallied pi	went and go 2". Shot pip 910', 1806', Fished wir orked pipe log 42" casing, ole to 300', hole to 40!,	overshope at 2581 no change e line out ose. Pul. 64 joints	t, ran it , worked p in tension t of hole, led 40 join s total. Coridge and	oipe. i. nts :leared ran	
PLUGGING	COMPLETE.					
Name of Plugging Contractor Address		on is necessary, use BAC ING PULLI NG C				
STATE OF	EL J. KNIGHT says: That I have knowledge	employee of of the facts, statement. So help me Goo	owner) or (ownents, and matt	mer or operator)		
SUBSCRIBED AND SWORN TO before	//		SE, KANSAS	(Address)	67 W	Public.
My commission expires.	2,1970	. ()	•		wotary	ruduc.

MILL LOG

SCHEUFLER #5

The Manderson Oil Company of al - owners - Jakenfler #5

ES Cor.

Secritors 16-20-11W Barton Charty, Kansas

Elevation 1771 BE

Tope at Rotery Bushing

2643 Topeks. His extra services 2900 Brown Idne 3034 Lansing Ar bunkin

Pipe Records

8 5/8" set at 324"

4 1 AT most set 32944

Figure indicate between of fewerther

128 Sand and Gravel G an

165 Shalm

200 Gravell cool mossic

Alif Red bed and shalls

540 Aulydeste

1015 Shele and shalls

1200 Sals and shelle

1425 Shelm and shalls

2120 Line

2565 Meals and lines

2750 Idos and shale

2935 Lives

3040 Shale said line

3296 Mass

3296 79 28

CARLS TOOL WAR.

Gloom out and drill somewith 3296-3305} Man

STATE OF MANUAL COUNTY OF SEDEMINE

I, J. A. Handerment, Secretary of The Manderson \$11 Company, park camps of the above described wall, being first only sworm on onth, declared that I have knowledge of the facts, statements, and matters because dentalised pertaining to the log of the above described well, and that the sime are teran and cerrocts

Sween and muheeribed to before me this

My commission expired April 28, 1956.

WAYNE E. WALCHER

Consultant Guologist CENTRAL BUILDING WICHITA, KANSAS

WELL REPORT

November 22, 1950

The Henderson Cil Company No. 5 Scheufler SE SE SE 16-20-11W, Barton County, Kansas

Zero - - - - Drive Bushing, 2' above derrick floor Elev. 1771 - " "

Soft	2625-41	Sand, gray, fine-grained, misadeous, no stain.
Topeks	2641 (-870)	
Soft	2738-40	Lime, buff, pin-hole porosity, no stein.
Soft	2823-38	Lime, cream, finely colicastic porosity,
Soft	2861-73	no stain. Lime, cream-white, compact and chalky, poor porceity, no stain.
Heebner	2908 (-1137)	you porover all my address
Teronte	2926	
Base Oread	2940	
Brown Lime	3034 (-2263)	
Lensing	3052 (-1281)	
Stain	3061-65	Lime, white-tan, dense with rare sucrose
		areas, fair spotted stain. Hocker.
Stain	3075-78	Lime, semi-colicastic, tight, spetted
		dark stein. Few pieces poorly developed inter-colite porceity, faint oder.
D. S. T.	3062-85	Open 30 minutes, recevered 15' mud, few
		spots heavy oil. We BEP.
Stein	31.35-40	Line, coersely colienstic perceity, in part sucrose, light spotted stain, breaks
		free cil, faint oder
Stein	3182-90	Line, poorly developed colioastic porosity,
		trace free oil, feir oder and rainbow.
D. S. T.	3182-3301	Open 30 minutes, recovered 10' mui, very slightly oil out. No BHP.
Stain	3281-85	Lime, fine, dense, with trace sugary areas
		of poor porosity and dark stain, odor,
		no free oil.
No Conglomerate Arbuckle	3293 (-1522)	
ALMERTA	3293-96	Dolomite, light gray, medium to course
		cryst, predominately tight but few pieces
		show fair vugular porosity, light stain,
Datamer W. B	3296	trace free oil and good oder.
Rotary T. D.	2470	4 Occurate a 252230

WAYNE E. WALCHER

Consultant Geologist

WICHITA, KANBAS

On top of the Arbuckle & -1522 this test is 9 feet higher than the east offset and 12' higher than the north offset.

Before final abandonment, the shows of oil listed in the Lansing-Manses City should be tested. They all seem to lack permeability, or at least three sense in this well and one in the east offset have failed to give up fluid on B.S.T. However, and treatment might prove commercial.

WAYNE E. WALCHER

Consultant Geologist

DENTRAL BUILDING

The Henderson Oil Company No. 5 Scheufler SE SE SE 16-20-11W, Barton County, Kenses

SE SE SE 16-	-20-11W, Berton County, Kens	88
	TIME LOG	
ENSL Te	Minister Addition	zenezka ,
2600 - 2600	4-6-4-2-1-2-2-2-2-2	
2620	2-2-2-2-2-2-2-3-2-2	
2630 2640	2-2-2-2-3-2-3-1-2 1-3-1-2-1-2-2-2-3-2	
2650	2-4-8-5-4-6-2-5-6-5	
2660	6-4-3-2-3-2-3-6-4-6	
2670	6-5-5-6-6-7-7-6-6-5	
2680	5-6-7-6-6-6-6-6-5-6	
2690	4-7-5-6-4-4-4-6-5-7	2000 m.s.
2690 - 2700	8-8-7-6-6-10-8-8-6-8	2700 - Trip
2720	7-5-7-4-6-5-4-6-7-6	
2730	4-6-6-7-5-5-6-4-5-5	
2740	4-4-4-4-5-7-6-6-2-4	
2750	10-12-6-6-5-5-6-10-5	
2760 2770	7-7-9-10-8-7-5-6-4-4	
2780	7-6-9-17-7-8-7-7-9-6	
2790	7-9-8-9-7-8-8-8-8-8	
2790 - 2800	9-7-9-8-9-9-10-9-7-5	
2810	6-8-9-9-9-30-9-9-8	
2820	9-9-8-5-6-30-9-7-9-7	
2830 2840	6655534578	
2850	8-7-7-8-9-7-8-10-9-5	
2860	7-6-8-8-8-10-9-8-9	
2870	7-de-5-b-B-5-de-b-b-5	
2880	6-5-6-8-9-8-9-9 9-10-10-8-10-9-8-9-9-7	
2890 - 2900	9-7-7-8-8-10-10-6-6-5	2897 - Trip
2910	6-5-6-5-5-4-4-2-1	
2920	2-6-10-6-9-5-3-3-4-3	
2930 2940	3-4-2-2-3-4-4-4-4 5-4-4-4-5-4-5-7-5	
2950	5-4-4-3-4-3-2-3-2-3	
2960	3-4-3-4-3-4-dale-3-4	
2970	hospitalindershirt 303 och och	
2980	3-3-4-3-3-3-4-3-3-4 4-4-4-5-3-5-4-3-5-4	
2990 - 3000	5-6-6-7-7-7-8-8-6-4	
3010	hodindula-5-d-5-bodind	
3020	3-4-3-4-2-3-4-3-3-4	
3030	5-4-5-5-5-4-3-3-4-4	
3040 3050	4-4-3-3-5-8-8-7-9-8 8-8-5-5-5-6-6-6	
3060	6-5-4-4-4-4-8-5-6	
3070	5-4-4-5-7-0-7-9-7	
3080	7-8-8-7-6-4-3-5-8-6	
3090	8-7-6-7-7-6-5-5-5-5	
3090 = 3100	7-5-6-5-6-6-5-5-5-5	
30.20	4-5-5-3-4-7-4-3-4-5	
3130	6-6-6-5-5-6-6-5-5	
3140	6-5-6-6-4-3-3-3-4-4	3136-40 - S.R.
37.50	6-6-5-5-3-3-4-5-3-2	3142 - Circ. 1 Bre
3160 3170	6-6-8-3-6-7-7-7-7-5	
30.80	8-9-9-6-5-7-	
3190	7-3-3-dadododododo 3	
3190 - 3200	4-6-9-7-8-5-8-7-7-5	

WAYNE E. WALCHER

Consultant Geologist
BENTRAL BUILDING
WIGHITA, KANSAS

The Henderson Cil Company No. 5 Schoufler SE SE SE 16-20-11W, Barton County, Kansas

Exem	Ta_	Himtes	7303 100	Beenche
3220	9830 3240 3250 3260 3270 3280 3290 3296	5-6-5-3-3-2-3-4-5-6 5-6-5-3-4-5-6 8-6-6-3-3-6-5-3-4-6 5-5-5-5-5-5-5-5-5-7-5 5-5-6-5-7-6-7-7-8-6 6-5-5-4-5-8-6-4-4-5 7-6-7-5-7-6		3280 - S.R. 3280 - S.R. 3281 - S.R. 3296 - Circ. for Spin 1 Res 3293 - Girc. Spin 1 Res 3294 - S.R.