

DISTRICT CONSERVATION AGENT'S REPORT

*OR*

TO:

State Corporation Commission  
Conservation Division  
211 North Broadway  
Wichita, Kansas

FILE NO. \_\_\_\_\_

LOCATION NE-27N-32W

SEC. 26 TWP. 18 RGE. 9W

Dry Hole  Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have this date completed supervision of plugging of:

Well No. 1 Lease Kernel-Hayes 527 Beacon Bldg.

Operator Brandmore Drilling Co Address Wichita Kansas

Field \_\_\_\_\_ County Rice

Total Depth 3252 Feet.

Plugging Contractor Operator

Plugging Contractor's License No. \_\_\_\_\_

Address \_\_\_\_\_

(Describe Briefly the manner in which the well was plugged)

*Grouted pits and circulated, hole made solid at 200', 15 cu cement thru 6 joints drill pipe, mud to 5' bridge, 5 cu cement at Top.*

*Paul D. ...*  
District Conservation Agent

Date 6-8-1957

**PLUGGING**  
FILE SEC. 26 T. 18 R. 9W  
BOOK PAGE 19 LINE 21

**RECEIVED**  
STATE CORPORATION COMMISSION  
JUN 10 1957 6-10-1957  
CONSERVATION DIVISION