4-071079

200 COLORADO DERBY BUILDING	API number: 15 12-2-39 E2 E2 SE /4 SEC. 10 , 20 S, 11 W 660
Operator license# <u>3613</u>	Lease Panning B well # 20
Operator: <u>Hallwood Petroleum</u> , <u>Inc</u> .	County <u>Barton</u>
	Well total depth <u>3280</u> feet Conductor Pipe: <u>0</u> inch @ <u>0</u> feet Surface pipe 8 5/8 Inch @ <u>480</u> feet
Aband. oil well <u>X</u> , Gas well <u></u> , Inpu	ıt well, SWD, D & A
Plugging contractor: <u>Halliburton Service</u>	ces-Klima Well Service License#
Address: Pratt, Kansas	- Claflin, Kansas
Company to plug at: Hour: P.M. Day:	28 Month: December Year: 93
Plugging proposal received from: George Hutton - Rick Popp	
Company: Hallwood Petroleum, Inc.	Phone: 316-792-2756
3273' w/75 sxs. cement. 5 1/2" casing sanded off w/4 sxs. frack sand. Open hole - casing holes @ 861' - 1079' -490' - 218'. Proposal by Dennis Hamel - 12 sxs. bentonite gel - 275 sxs. 60/40 pozmix - 10% gel - 1/4# F.C. Pump in with pump truck. Spot and displace all cement and gel through tubing. Load both 5 1/2" casing and 5 1/2" x 8 5/8" annulus. Shut in under pressure. Plugging Proposal Received by: Dennis L. Hamel	
Plugging operations attended by agent?	All[X], Part[], None[]
Completed: Hour: 2:00P.M., Day: 28, Mor	nth: <u>December</u> , Year: 93
Actual plugging report: Hallwood Petroleum ran 2 7/8 tubing to 1025'. Couldn't get down - worked on hole two days plus - also tried 1 1/4" tubing casing bad at 1025'. Don Butcher gave permission to plug at that depth. 5 1/2" casing was perferated @ 520'. All cement was pumped in with pump truck. Spotted through 2 7/8" tubing at 1025'- spotted 125 sxs.class A cement - 150 sxs. pozmix - 10% gel - 12 sxs. gel - 125 sxs pozmix - 6% gel - 250 sxs. pozmix with salt - 200 sxs. cement - 200 sxs multi cement R.C. w/8 sxs. hulls. Cement circulated out of 5 1/2" casing and 5 1/2" x RECEIVED 8 5/8" annulus - spotted another 25 sxs. then squeeze casing with an STATE CORPORATION COM additional 100 sxs. 60/40 pozmix - 2% gel. Max. Pressure 250 P.S.I. Remarks: Total cement 1175 sxs Cemented by Halliburton Cement. JAN 05 1994 Condition of casing(in hole): GOOD BAD x Anhy.plug: YES x NO Bottom plug(in place): YES, CALC, NO Dakota plug: YES x , NO Bottom plug(in place): YES, CALC, NO Dakota plug: YES x , NO Plugged through TUBING x , CASING Elevation:GL Wichya, Kansas I did x 0/ add not [] observe the plugging	
DATE 1-6-94	(agent)
WV. NO. 39631	Form CP-2/3