

KCC OIL/GAS REGULATORY OFFICES

Inspection Date 05/16/2017 District: 3 Incident Number: 5782

- New Situation  Lease Inspection
- Response to Request  Complaint
- Follow-up  Field Report

Operator License No: 32044 API: 15-073-19928-0000 Q3 Q2: Q1:

Operator Name: Trimble & Maclaskey SEC 22 TWP 23 RGE 13 RGEDIR e

Address: P.O Box 171 FSL:

City: Gridley FEL:

State Ks Zip Code: 66852 Lease: Shambaugh Well No.: 2,3

Phone contact: 620 836 2000 County: Gw

Reason for Investigation:

Well inventory

Problem:

wells could not be found

Persons contacted:

Jim Thweet Prod. Supt.

Findings:

Used old lease map, went to locations found possible well locations, metal detector was useless to much junk iron around locations wells appeared to be plugged.

Actions / Recommendation

Follow-up Required

Deadline Date:

Remove wells from inventory

Photo's Taken: 0

RBDMS  KGS  TA DBF

Report Prepared By: Mike Heffern

T1 DBF  District Files  Courthouse

Position: E.C.R.S.