

KCC OIL/GAS REGULATORY OFFICES

Inspection Date 05/16/2017 District: 3 Incident Number: 5782

- New Situation Lease Inspection
- Response to Request Complaint
- Follow-up Field Report

Operator License No: 32044 API: 15-073-19929-0006 Q3 Q2: Q1:
 Operator Name: Trimble & Maclaskey SEC 22 TWP 23 RGE 13 RGEDIR e
 Address: P.O Box 171 FSL:
 City: Gridley FEL:
 State Ks Zip Code: 66852 Lease: Shambaugh Well No.: X2,3
 Phone contact: 620 836 2000 County: Gw

Reason for Investigation:

Well inventory

Problem:

wells could not be found

Persons contacted:

Jim Thweet Prod. Supt.

Findings:

Used old lease map, went to locations found possible well locations, metal detector was useless to much junk iron around locations wells appeared to be plugged.

Actions / Recommendation

Follow-up Required

Deadline Date:

Remove wells from inventory

Photo's Taken: 0

RBDMS KGS TA DBF Report Prepared By: Mike Heffern
 T1 DBF District Files Courthouse Position: E.C.R.S.