KCC OIL/GAS REGULATORY OFFICES Inspection Date 05/16/2017 District: 3 Incident Number: 5782 ✓ New Situation Lease Inspection Response to Request Complaint ☐ Follow-up ☐ Field Report Operator License No: 32044 API: 15-073-19927-0000 Q3 Q2: Q1: Operator Name: Trimble & Maclaskey SEC 22 TWP 23 RGE 13 RGEDIR e Address: P.O Box 171 FSL: City: Gridley FEL: State Ks Zip Code: 66852 Lease: Shambaugh Well No.: 1,2,3 Phone contact: 620 836 2000 County: Gw Reason for Investigation: Well inventory Problem: wells could not be found Persons contacted: Jim Thweet Prod. Supt. Findings: Used old lease map, went to locations found possible well locations, metal detector was useless to much junk iron around locations wells appeared to be plugged. **Actions / Recommendation** Follow-up Required **Deadline Date:** Remove wells from inventory Photo's Taken: KGS **✓** RBDMS ☐ TA DBF Report Prepared By: Mike Heffern District Files ☐ T1 DBF Courthouse Position: <u>E.C.R.S.</u>