## KCC OIL/GAS REGULATORY OFFICES Inspection Date 05/16/2017 District: 3 **Incident Number:** 5779 New Situation Lease Inspection Response to Request Complaint Follow-up Field Report Operator License No: 32044 Q3 sw Q2: sw Q1: se API: 15-207-19403-00-00 Operator Name: Trimble & Maclaskey LLC SEC 24 TWP 23 RGE 13 RGEDIR e Address: P.O. Box171 FSL: 289 City: Gidley FEL: 2305 State Ks Zip Code: 66852 Lease: Jones Well No.: 4 Phone contact: 620 836 2000 County: Wo Reason for Investigation: Well inventory list Problem: Operator had well listed on license,after checking lease for well determined that an error had occured. Persons contacted: Jim Thweet Prod Sup. Findings: Checked location, found signs of an old pit, gps location 289' FSL, 2305 FEL, Used metal detector did not pick any signs of casing. Actions / Recommendation Follow-up Required **Deadline Date:** remove well from well inventory Photo's Taken: 0

Report Prepared By: Mike Heffern

E.C.R.S.

Position:

☐ KGS

✓ District Files

☐ TA DBF

Courthouse

**✓** RBDMS

☐ T1 DBF