40R

TO:	API number: 15-153-20,791-00-00
STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING	E2 SW SW /4 SEC. 01 , 01 S, 35 W
200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	feet from S section line feet from E section line
Wilding Tambrib 07202	1990 reet from E Section fine
Operator license# 5135	Lease_ <b>Sis</b> well #_1
Operator: John O. Farmer, Inc.	County Rawlins 1222 foot 140.72
Address: 370 W. Wichita Avenue	well total depth <u>4330</u> feet
Box 352 Russell, Kansas 67665	Conductor Pipe: 8 5/8 inch @ 300 feet Surface pipe 170 feet @ 283 feet
Aband. oil well, Gas well, Inp	
Plugging contractor: Abercrombie R.T.D	., Inc. License# 30684
Address:	
Company to plug at: Hour: 1:45P.M. Day:	9 Month: August Year: 92
Plugging proposal received from: Bill	Craid
Company: John O. Farmer, Inc.	Phone: 913-483-3144
Were: Order 210 sks. 60/40 pozmix -	6% gel 3% cal. cl 1 sk.
flocele and 8 5/8" plug. Spot with dr	ill pipe with no less than 36 vis.
mud between all plugs with good circul	ation and no fluid loss.
Plugging Proposal Received by: Gilber	t a acharle
Plugging operations attended by agent?	All[ ], Part[ ], None[ X ]
	nth: Contembor Voor: 00
	nth: September , Year: 92
Actual plugging report:	
Actual plugging report:  1st. plug @ 3037' w/25 sks.	
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.	
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.  3rd. plug @ 1100' w/100 sks.  4th. plug @ 300' w/25 sks.	STATE RECEI
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.  3rd. plug @ 1100' w/100 sks.  4th. plug @ 300' w/25 sks.  5th. plug @ 40' w/10 sks.	STATE RECEI
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.  3rd. plug @ 1100' w/100 sks.  4th. plug @ 300' w/25 sks.  5th. plug @ 40' w/10 sks.  15 sks. in Rathole.	STATE COMPORATION COMMISSION
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.  3rd. plug @ 1100' w/100 sks.  4th. plug @ 300' w/25 sks.  5th. plug @ 40' w/10 sks.	STATE CORPORATION COMMISSION SEP 16-150-792
Actual plugging report:  1st. plug @ 3037' w/25 sks. 2nd. plug @ 1700' w/25 sks. 3rd. plug @ 1100' w/100 sks. 4th. plug @ 300' w/25 sks. 5th. plug @ 40' w/10 sks. 15 sks. in Rathole. 10 sks. in Mousehole.	STATE CORPORATION COMMISSION SEP 16-15092
Actual plugging report:  1st. plug @ 3037' w/25 sks. 2nd. plug @ 1700' w/25 sks. 3rd. plug @ 1100' w/100 sks. 4th. plug @ 300' w/25 sks. 5th. plug @ 40' w/10 sks. 15 sks. in Rathole. 10 sks. in Mousehole.  Remarks: Allied	STATE COMPORATION COMMISSION SEP 1 6 190,972  CONSERVATION
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.  3rd. plug @ 1100' w/100 sks.  4th. plug @ 300' w/25 sks.  5th. plug @ 40' w/10 sks.  15 sks. in Rathole.  10 sks. in Mousehole.  Remarks: Allied  Condition of casing(in hole):GOOD B	STATE CORPORATION COMMISSION  SEP 16-15972  CONSERVATION DIVISION  AD Anhy. plug: YES X NO WORLD BY BOTH STATE OF THE PROPERTY
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.  3rd. plug @ 1100' w/100 sks.  4th. plug @ 300' w/25 sks.  5th. plug @ 40' w/10 sks.  15 sks. in Rathole.  10 sks. in Mousehole.  Remarks: Allied Condition of casing(in hole):GOODB Bottom plug(in place):YES,CALC	STATE CORPORATION COMMISSION  SEP 16 1999  CONSERVATION CONTROL  WIGHING HARDSON  AND DAKOTA PLUG: YES X NO  DAKOTA PLUG: YES X NO  STATE CORPORATION COMMISSION  NO DAKOTA PLUG: YES X NO  STATE CORPORATION COMMISSION  NO DAKOTA PLUG: YES X NO  STATE CORPORATION COMMISSION  NO DAKOTA PLUG: YES X NO
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.  3rd. plug @ 1100' w/100 sks.  4th. plug @ 300' w/25 sks.  5th. plug @ 40' w/10 sks.  15 sks. in Rathole.  10 sks. in Mousehole.  Remarks: Allied Condition of casing(in hole):GOOD B Bottom plug(in place):YES,CALC_ Plugged through TUBING, CASING	STATE COMPORATION COMMISSION  SEP 16 199972  CONSERVATION DIVISION  AD Anhy.plug:YES X NO WIGHING MARGINE  NO Dakota plug:YES X, NO  Elevation: 2843 GL
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.  3rd. plug @ 1100' w/100 sks.  4th. plug @ 300' w/25 sks.  5th. plug @ 40' w/10 sks.  15 sks. in Rathole.  10 sks. in Mousehole.  Remarks: Allied Condition of casing(in hole):GOODB Bottom plug(in place):YES,CALC_ Plugged through TUBING, CASING  I did[	STATE COMPORATION COMMISSION  SEP 16 199972  CONSERVATION DIVISION  AD Anhy.plug:YES X NO WIGHING MARGINE  NO Dakota plug:YES X, NO  Elevation: 2843 GL
Actual plugging report:  1st. plug @ 3037' w/25 sks.  2nd. plug @ 1700' w/25 sks.  3rd. plug @ 1100' w/100 sks.  4th. plug @ 300' w/25 sks.  5th. plug @ 40' w/10 sks.  15 sks. in Rathole.  10 sks. in Mousehole.  Remarks: Allied Condition of casing(in hole):GOOD B Bottom plug(in place):YES,CALC_ Plugged through TUBING, CASING	STATE COMPORATION COMMISSION  SEP 16 199972  CONSERVATION DIVISION  AD Anhy.plug:YES X NO WIGHING MARGINE  NO Dakota plug:YES X, NO  Elevation: 2843 GL