JUN 0 1 2004

KCC WICHITA

То:		API NUMBER	15.12	5.19878	3.00
STATE CORPORATION COMM	IISSION	NE SW NW	_Sec/Twp/Rge	22-34-15E	
Wichita State Office Bldg PLUGGING SECTION		3811	3811 feet from south section line		
130 S. Market, Room 2078 Wichita, Kansas 67202		4472	feet from e	east section line	
TECHNICIAN'S PLUGGING RE	PORT	Lease/Well#	HESTER #	JCH42	
Operator License # \(\frac{10}{10}\)		County	MONTGO	MERY	
Operator: STATE OF KANSAS	Refund	Well Total Depth		<u>250</u> fe	et
Name & DISTRICT #3		Production Pipe:	2"	Size Feet	250
Address CHANUTE, KS		Surface Casing:	8"	_Size Feet N	<u>'A</u>
AB oil well X Gas Well	SWD W	ell/ Input Well		D & A	
Other well as hereinafter indicate	ed: OLD WI	ELL ALREADY PLUC	GGED, BUT	NO REPORT N	MADE.
Plugging Contractor: <u>ELMORE</u>	S, INC.	·····		Lic. #	32884
Address: P. O. BOX 87, SED	AN, KS 67361				
Company to plug at: Hour:	Day:	4	Month:	5	2004
Plugging proposal received from	:				
. lagging proposal reserved from			DI		
Company Name:			Phone:		
			_Pnone:		
Company Name:	Plugging Proposal F		_Pnone:	/E	
Company Name: Were:	Plugging Proposal F	Received by:	RON ROW	TECHNICIAN	
Company Name:  Were:  Plugging attended by Agent:	Plugging Proposal F	Received by:	RON ROW	TECHNICIAN None	2004
Company Name:  Were:  Plugging attended by Agent:  Operations Completed: Hour:	Plugging Proposal F All Day:	Received by: Part 4	RON ROW X Month:	TECHNICIAN None 5	2004 JI D
Company Name:  Were:  Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report:	Plugging Proposal F All Day: TRIED TO WASH 1	Received by:Part4 1" PIPE DOWN INTO	RON ROW  X  Month:  2" PIPE T	TECHNICIAN None 5 O TD, BUT COL	JLD
Company Name:  Were:  Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: NOT GET BELOW 30, AND DR	Plugging Proposal F AllDay:TRIED TO WASH 1	Received by: Part 4" PIPE DOWN INTO	RON ROW  X  Month:  2" PIPE TO	TECHNICIAN None 5 O TD, BUT COL	JLD E OF 2",
Company Name:  Were:  Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report:	Plugging Proposal F AllDay:TRIED TO WASH 1	Received by: Part 4" PIPE DOWN INTO	RON ROW  X  Month:  2" PIPE TO	TECHNICIAN None 5 O TD, BUT COL	JLD E OF 2",
Company Name:  Were:  Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  NOT GET BELOW 30, AND DR  BUT DRILLING ON CEMENT @	Plugging Proposal F AllDay: _TRIED TO WASH 1 ILLING ON CEMENT.	Received by: Part 4 1" PIPE DOWN INTO TRIED TO WASH	RON ROW  X  Month:  D 2" PIPE TO  DOWN BEH  OF 2" WITH	TECHNICIAN None 5 O TD, BUT COU	JLD E OF 2", MENT.
Company Name:  Were:  Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: NOT GET BELOW 30, AND DR BUT DRILLING ON CEMENT @	Plugging Proposal F AllDay: TRIED TO WASH 1 ILLING ON CEMENT. 15'. TOPPED-OFF I	Received by: Part 4 I" PIPE DOWN INTO TRIED TO WASH INSIDE & OUTSIDE	RON ROW  X  Month:  D 2" PIPE TO  DOWN BEH  OF 2" WITH	TECHNICIAN None 5 O TD, BUT COU	JLD E OF 2", MENT.
Company Name:  Were:  Plugging attended by Agent:  Operations Completed: Hour:  Actual Plugging Report:  NOT GET BELOW 30, AND DR  BUT DRILLING ON CEMENT @	Plugging Proposal F AllDay: TRIED TO WASH 1 ILLING ON CEMENT. 15'. TOPPED-OFF I	Received by: Part 4 I" PIPE DOWN INTO TRIED TO WASH INSIDE & OUTSIDE	RON ROW  X  Month:  D 2" PIPE TO  DOWN BEH  OF 2" WITH	TECHNICIAN None 5 O TD, BUT COU	JLD E OF 2", MENT.
Company Name:  Were:  Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: NOT GET BELOW 30, AND DR BUT DRILLING ON CEMENT @  THIS REPORT IS FOR HANDL ON THIS EVIDENTLY PREVIOUS Remarks: CONTROL # 200400	Plugging Proposal F All Day: TRIED TO WASH 1 ILLING ON CEMENT. 15'. TOPPED-OFF I	Received by:  Part  1" PIPE DOWN INTO TRIED TO WASH INSIDE & OUTSIDE  VOICE & NO PLUG	RON ROW  X  Month:  D 2" PIPE TO  DOWN BEH  OF 2" WITH	TECHNICIAN None 5 O TD, BUT COU	JLD E OF 2", MENT.
Company Name:  Were:  Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: NOT GET BELOW 30, AND DR BUT DRILLING ON CEMENT @  THIS REPORT IS FOR HANDLE ON THIS EVIDENTLY PREVIOUS  Remarks: CONTROL # 200400 (If additions)	Plugging Proposal F AllDay:TRIED TO WASH 1 ILLING ON CEMENT. 15'. TOPPED-OFF I ING OF FEE FUND IN JSLY PLUGGED WEI 024-42 CONTRACT #	Received by:  Part  1" PIPE DOWN INTO TRIED TO WASH INSIDE & OUTSIDE  VOICE & NO PLUG	RON ROW  X  Month:  D 2" PIPE TO  DOWN BEH  OF 2" WITH	TECHNICIAN None 5 O TD, BUT COU	JLD E OF 2", MENT.
Company Name:  Were:  Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: NOT GET BELOW 30, AND DR BUT DRILLING ON CEMENT @  THIS REPORT IS FOR HANDLE ON THIS EVIDENTLY PREVIOUS  Remarks: CONTROL # 200400 (If additions)	Plugging Proposal F All Day: TRIED TO WASH 1 ILLING ON CEMENT. 15'. TOPPED-OFF I	Received by:  Part  1" PIPE DOWN INTO TRIED TO WASH INSIDE & OUTSIDE  VOICE & NO PLUG	RON ROW  X  Month:  D 2" PIPE TO  DOWN BEH  OF 2" WITH	TECHNICIAN None 5 O TD, BUT COU	JLD E OF 2", MENT.
Company Name:  Were:  Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: NOT GET BELOW 30, AND DR BUT DRILLING ON CEMENT @  THIS REPORT IS FOR HANDLE ON THIS EVIDENTLY PREVIOUS  Remarks: CONTROL # 200400 (If additions)	Plugging Proposal F AllDay:TRIED TO WASH 1 ILLING ON CEMENT. 15'. TOPPED-OFF I ING OF FEE FUND IN JSLY PLUGGED WEI 024-42 CONTRACT #	Received by:  Part  1" PIPE DOWN INTO TRIED TO WASH INSIDE & OUTSIDE  VOICE & NO PLUG	RON ROW  X  Month:  D 2" PIPE TO  DOWN BEH  OF 2" WITH	TECHNICIAN None  5  O TD, BUT COU HIND/BACKSIDE H 4 SACKS CEN ORT DONE BEF	JLD E OF 2", MENT.