## KCC OIL/GAS REGULATORY OFFICES

Date: <u>07/20/17</u>	District: 1	Case #:
	New Situation	Lease Inspection
	Response to Request	Complaint
	Follow- <del>Up</del>	Field Report
Operator License No: 3842	API Well Number: <u>15-10</u>	01-22595-00-00
Op Name: Larson Engineering, Inc., dba Larson Operating Company	Spot: <u>SE-SW-NW-NW</u>	See <u>7                                  </u>
Address 1: 562 W. State Rd. 4	4137	Feet from N/ S Line of Section
Address 2:	4494	Feet from FE/W Line of Section
City: Olmitz	GPS: Lat: <u>38.42067</u>	Long: <u>100.46355</u> Date: <u>7/20/17</u>
State: KS Zip Code: 67564 -8561	Lease Name: Paris	Well #: <u>2-7</u>
Operator Phone #: <u>(620) 653-7368</u>	County: <u>Lane</u>	
Reason for Investigation:		
Company requested a state witness to the alternate II cementing job.		
Problem:		
Alternate II cementing requirements have not been met.		
Persons Contacted:		
Kyle Robe.	de d	
Findings:		700000
		· · · · · · · · · · · · · · · · · · ·
TD-4675'. 8 5/8" set @ 265'.		
4 1/2" set @ 263.		
Opened port collar @ 2092'.		
Pumped 265 sx SMD cement, circulating 20 sx to the pit.		
Closed port collar.		
	WWW.	
Action/Recommendations: Follow	Up Required	Date:
None. Alternate II cementing requirements have been met.		
Notice. Alternate in cementing requirements have been met.		
Section de la se	**************************************	1-7-7-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
Verification Sources:		Photos Taken: ()
✓RBDMS ✓KGS TA	A Program	
himi	ourthouse By:	
Other: On-site witness.	<u>Eric</u>	MacLaren
Retain 1 Copy District Office		
Send 1 Copy to Conservation Division JUL 2 1 20	17 N	Form;
KCC DODGE C	TTY /W	
	1	