

KCC OIL/GAS REGULATORY OFFICES

Date: 03/03/15

District: 01

Case#: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 32331

API Well Number: 15-135-25838-00-00

Op Name: DK Operating Inc.

Spot: SW-SW-NW Sec 18 Twp 20 S Rng 22  E /  W

Address 1: 621 Benton ST.

2428 Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

138 Feet from  E /  W Line of Section

City: Jetmore

GPS: Lat: \_\_\_\_\_ Long: \_\_\_\_\_ Date: 3/3/15

State: KS Zip Code: 67854 -

Lease Name: Star Well #: 1-18

Operator Phone #: (620) 357-6152

County: Ness

Reason for Investigation:

Witness Alt. II

Problem:

None

Persons Contacted:

\_\_\_\_\_

Findings:

TD @ 4325'.  
 8.625 @ 222' W/150 sx cmt.  
 5.5 @ 4324' W/145 sx cmt.  
 Port Collar @ 1436' W/165 sx cmt-20 sx to the pit.  
 SMD-1/4# Floseal by Swift Services.

Received  
 KANSAS CORPORATION COMMISSION  
**MAR 19 2015**  
 CONSERVATION DIVISION  
 WICHITA, KS

3-19-15

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt II requirements have been met.

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Larry Harris

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

**RECEIVED**  
**MAR 16 2015**  
 KCC DODGE CITY

MA

JA

Form: \_\_\_\_\_

Date: 03/03/15

District: 01

License #: 32331

Op Name: 32331

Spot: SW-SW-NW Sec 18 Twp 20 S Rng 22 E  W

County: Ness

Lease Name: Star Well #: 1-18

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No  Ness

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25838-00-00	2409' FNL 143' FWL	SW SW NW	38.31313-99.80539	1-18	Cement circulated to pit