

KCC OIL/GAS REGULATORY OFFICES

Date: 04/29/15

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 30742
 Op Name: Palomino Petroleum, Inc.
 Address 1: 4924 SE 84th ST
 Address 2: _____
 City: Newton
 State: Kansas Zip Code: 67114 -8827
 Operator Phone #: (316) 799-1000

API Well Number: 15-135-25862-00-00
 Spot: SENWSESE Sec 24 Twp 16 S Rng 16 E / W
 886 (896) Feet from N / S Line of Section
 883 (885) Feet from E / W Line of Section
 GPS: Lat: 38.64058 Long: 100.03133 Date: 4/29/13
 Lease Name: Nuttle Trust Well #: 1
 County: Ness

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

Findings:

8-5/8"@216"W/165sxs
 TD@4665'
 5-1/2"@4662"W/195sxs
 Port Collar@1908"W/160sxs-smd-1/4#floseal-2%cc-15sxs to pit

Action/Recommendations:

Follow Up Required Yes No

Date: _____

None, Alt.II requirements have been met.

KCC WICHITA
 MAY 08 2015
 RECEIVED

5-8-15

Verification Sources:

Photos Taken: _____

- | | | |
|---------------------------------------|--|-------------------------------------|
| <input type="checkbox"/> RBDMS | <input type="checkbox"/> KGS | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input checked="" type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| Other: _____ | | |

By: Michael Maier
 Michael Maier

SA

Retain 1 Copy District Office
 Send 1 Copy to Conservation Division

RECEIVED
 MAY - 4 2015
 KCC DODGE CITY

Form: _____

Date: 04/29/15

District: 01

License #: 30742

Op Name: 30742

Spot: SENWSESE Sec 24 Twp 16 S Rng 16 E W

County: Ness

Lease Name: Nuttle Trust Well #: 1

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25862-00-00	896FSL 885FEL	SENWSESE	38.64058-100.03133	1	Alt. II done cement circulated to surface

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: _____