

test hole report Layne-Western Company, Inc.

				<i>y</i> 3,250
eHamm	Quarries	5		TEST HOLE
A-439				No. 2-78
				Driller V. Campbell
SE1/4,	SE 1			.7E, 300' West of Test Hole 1-78
•				
			TEST LOG	
то	MARSH - FUNNEL - VISCOSITY	MUD PIT	An •	Static Water Level 28 Measure Hours After Completion
	SECONDS INCHES			FORMATION
1.0'			Topsoil	,
14.0'			Brown silty clay, stiff	
29.0'			Brown silty clay, soft	
34.0'			Gray silty clay	
35.0'			Brown med. to coarse sand	
40.0'	35	1"	Same	
45.0'	47	1"	Gray brown med. to coarse sand	
47'4"	47	1/2"	Gray brown med. to	fine sand
			Gray brown weathere	d limestone
Total d	epth			
Por	table			· · · · · · · · · · · · · · · · · · ·
e of Pit		×_		X X
	Pore of Pit	### A-439 Grantville	A-439	Grantville State SE1/4, SE 1/4, SET. 16, T11s, R1 Distance and Direction from Permanent Landtmark or a second state of the