

30 - 12 21E  
SE SE

Frank Steele

195

Co - Leavenworth

LEE Hendee

WATER WELL

6xxx 58'

|                  |                        |
|------------------|------------------------|
| sdv clay         | 28                     |
| quicksand        | 58                     |
| shale            | 71                     |
| lime             | 92                     |
| slate (Euboa sh) | 98 enough wtr for well |
| lime             | 105                    |
| shale            | 110                    |
| lime             | 111                    |
| shale            | 121                    |
| lime             | 191                    |
| shale            | 193                    |
| lime             | 195 T. D.              |

X

30-12-21E

County

Sec. 30 T. 12 R. 21E  
Loc. SE SE

Farm Frank Steele

Total Depth 195

Comp. 1930's (estim)

County Leavenworth

Comm.  
Shot or Treated  
Contractor Hendee  
Issued

WATER WELL



|        |                      |
|--------|----------------------|
| Casing |                      |
| 20 in. | 10 in.               |
| 15 1/2 | 8 1/4                |
| 12 1/2 | <del>4 5/8</del> 58' |
| 13 3/8 | 5 3/16               |

Elevation  
Production

Figures Indicate Bottom of Formation

|           |                        |
|-----------|------------------------|
| sdv clay  | 28                     |
| quicksand | 58                     |
| shale     | 71                     |
| lime      | 92                     |
| slate     | 98 enough wtr for well |
| lime      | 105                    |
| shale     | 110                    |
| lime      | 111                    |
| shale     | 121                    |
| lime      | 191                    |
| shale     | 193                    |
| lime      | 195 T. D.              |