

1 LOCATION OF WATER WELL:	Fraction	Section Number	Township Number	Range Number
County: <u>Johnson</u>	<u>NE</u> $\frac{1}{4}$ <u>NW</u> $\frac{1}{4}$ <u>NE</u> $\frac{1}{4}$	<u>3</u>	T <u>13</u> S	R <u>24</u> <u>EW</u>

Distance and direction from nearest town or city street address of well if located within city?

121419 W. 95th Street, Lenexa

2 WATER WELL OWNER:	Board of Agriculture, Division of Water Resources
RR#, St. Address, Box # : <u>1437 S. Boulder</u>	Application Number:
City, State, ZIP Code : <u>Tulsa, Oklahoma 74119</u>	

3 LOCATE WELL'S LOCATION WITH AN "X" IN SECTION BOX:	4 DEPTH OF COMPLETED WELL: <u>9</u> ft. ELEVATION: <u>98.62</u>
	Depth(s) Groundwater Encountered 1. <u>DRY</u> ft. 2. ft. 3. ft.
	WELL'S STATIC WATER LEVEL <u>3.35</u> ft. below land surface measured on mo/day/yr <u>7/20/93</u>
	Pump test data: Well water was ft. after hours pumping gpm
	Est. Yield gpm: Well water was ft. after hours pumping gpm
	Bore Hole Diameter <u>8.25</u> in. to <u>TD</u> ft. and in. to ft.
	WELL WATER TO BE USED AS: 5 Public water supply 8 Air conditioning 11 Injection well
	1 Domestic 3 Feedlot 6 Oil field water supply 9 Dewatering 12 Other (Specify below)
	2 Irrigation 4 Industrial 7 Lawn and garden only <u>10</u> Monitoring well
	Was a chemical/bacteriological sample submitted to Department? Yes No <u>X</u> ; If yes, mo/day/yr sample was submitted
	Water Well Disinfected? Yes No <u>X</u>

5 TYPE OF BLANK CASING USED:	5 Wrought iron	8 Concrete tile	CASING JOINTS: Glued Clamped
1 Steel	6 Asbestos-Cement	9 Other (specify below)	Welded
<u>2 PVC</u>	7 Fiberglass		Threaded <u>X</u>
3 RMP (SR)			
4 ABS			
Blank casing diameter <u>4</u> in. to <u>3</u> ft. Dia in. to ft. Dia in. to ft.			
Casing height above land surface <u>0</u> in. weight lbs./ft. Wall thickness or gauge No. <u>Sch 40</u>			
TYPE OF SCREEN OR PERFORATION MATERIAL:	<u>7 PVC</u>	10 Asbestos-cement	
1 Steel	8 RMP (SR)	11 Other (specify)	
2 Brass	9 ABS	12 None used (open hole)	
3 Stainless steel			
4 Galvanized steel			
6 Concrete tile			
SCREEN OR PERFORATION OPENINGS ARE:	5 Gauzed wrapped	8 Saw cut	11 None (open hole)
1 Continuous slot	6 Wire wrapped	9 Drilled holes	
2 Louvered shutter	7 Torch cut	10 Other (specify)	
3 Mill slot			
4 Key punched			
SCREEN-PERFORATED INTERVALS: From <u>9</u> ft. to <u>6</u> ft. From ft. to ft.			
GRAVEL PACK INTERVALS: From <u>9</u> ft. to <u>2</u> ft. From ft. to ft.			

6 GROUT MATERIAL:	<u>1 Neat cement</u>	2 Cement grout	<u>3 Bentonite</u>	4 Other
Grout Intervals: From <u>0</u> ft. to <u>0.5</u> ft. From <u>0.5</u> ft. to <u>2</u> ft. From ft. to ft.				
What is the nearest source of possible contamination:	10 Livestock pens	14 Abandoned water well		
1 Septic tank	11 Fuel storage	15 Oil well/Gas well		
2 Sewer lines	12 Fertilizer storage	16 Other (specify below)		
3 Watertight sewer lines	13 Insecticide storage			
4 Lateral lines				
5 Cess pool				
6 Seepage pit				
7 Pit privy				
8 Sewage lagoon				
9 Feedyard				
Direction from well? <u>Southeast</u>	How many feet? <u>40</u>			

FROM	TO	LITHOLOGIC LOG	FROM	TO	PLUGGING INTERVALS
<u>0</u>	<u>1.5</u>	<u>Asphalt</u>			
<u>1.5</u>	<u>3.5</u>	<u>Light brown/tan, high plastic, dry, silty clay</u>			
<u>3.5</u>	<u>4</u>	<u>Fragmented, dark brown/red, siltstone</u>			
<u>4</u>	<u>8</u>	<u>Light brown/tan, medium plastic, dry, silty clay</u>			
<u>8</u>	<u>9</u>	<u>Dark brown w/gray mottling, medium plastic, dry, silty clay</u>			
<u>9</u>		<u>Rock</u>			

7 CONTRACTOR'S OR LANDOWNER'S CERTIFICATION: This water well was (1) constructed, (2) reconstructed, or (3) plugged under my jurisdiction and was completed on (mo/day/year) <u>7/15/93</u> and this record is true to the best of my knowledge and belief. Kansas Water Well Contractor's License No. <u>517</u> This Water Well Record was completed on (mo/day/yr) <u>7/30/93</u> under the business name of <u>Groundwater Technology, Inc.</u> by (signature) <u>Dennis White</u>
--