


| | | | | | | | | |
|--|---|--------------------|---|--------------------------------|---|--------------------|-------------------------|--|
| 1 LOCATION OF WATER WELL: | Fraction County: Butler | NE $\frac{1}{4}$ | NE $\frac{1}{4}$ | NE $\frac{1}{4}$ | Section Number 36 | T 26 S | Range Number R 40 EW | |
| Distance and direction from nearest town or city street address of well if located within city? 1 mi N of Augusta on Ohio St - 2 E - 3/4 N - West Side | | | | | | | | |
| 2 WATER WELL OWNER: | Martin Coffman | | | | Board of Agriculture, Division of Water Resources | | | |
| RR#, St. Address, Box # | | | | | Application Number: | | | |
| City, State, ZIP Code | El Dorado, KS | | | | | | | |
| 3 LOCATE WELL'S LOCATION WITH AN "X" IN SECTION BOX: |  | | | | 4 DEPTH OF COMPLETED WELL 120 ft. ELEVATION: Depth(s) Groundwater Encountered 65 ft. 2. 100 ft. 3. ft. WELL'S STATIC WATER LEVEL 40 ft. below land surface measured on mo/day/yr 12/18/89 Pump test data: Well water was ft. after hours pumping gpm Est. Yield 4 gpm: Well water was ft. after hours pumping gpm Bore Hole Diameter 10 in. to ft., and in. to ft. WELL WATER TO BE USED AS: 5 Public water supply 8 Air conditioning 11 Injection well 6 Oil field water supply 9 Dewatering 12 Other (Specify below) 1 Domestic 3 Feedlot 7 Lawn and garden only 10 Monitoring well 2 Irrigation 4 Industrial | | | |
| Was a chemical/bacteriological sample submitted to Department? Yes No ✓ If yes, mo/day/yr sample was submitted | | | | | | | | |
| Water Well Disinfected Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> | | | | | | | | |
| 5 TYPE OF BLANK CASING USED: | 1 Steel 2 PVC | 3 RMP (SR) | 5 Wrought iron | 8 Concrete tile | CASING JOINTS: Glued Clamped Welded Threaded | | | |
| Blank casing diameter | 5 in. to | ft., Dia | in. to | ft., Dia | in. to | ft. | | |
| Casing height above land surface | +12 | | ft., weight 160 | lbs./ft. | Wall thickness or gauge No. | | | |
| TYPE OF SCREEN OR PERFORATION MATERIAL: | 1 Steel | 3 Stainless steel | 5 Fiberglass | 7 PVC | 10 Asbestos-cement | | | |
| 2 Brass | 4 Galvanized steel | 6 Concrete tile | 8 RMP (SR) | 11 Other (specify) | | | | |
| SCREEN OR PERFORATION OPENINGS ARE: | 1 Continuous slot | 3 Mill slot | 5 Gauzed wrapped | 8 Saw cut | 11 None (open hole) | | | |
| 2 Louvered shutter | 4 Key punched | 6 Wire wrapped | 9 Drilled holes | 10 Other (specify) | | | | |
| SCREEN-PERFORATED INTERVALS: | From 100 | ft. to 120 | ft., From ft. to ft. | ft. to ft. | | | | |
| GRAVEL PACK INTERVALS: | From 30 | ft. to 120 | ft., From ft. to ft. | ft. to ft. | | | | |
| 6 GROUT MATERIAL: | 1 Neat cement | 2 Cement grout | 3 Bentonite | 4 Other | | | | |
| Grout Intervals: | From 3 | ft. to 30 | ft., From ft. to ft., From ft. to ft. | ft. to ft. | | | | |
| What is the nearest source of possible contamination: | 1 Septic tank | 4 Lateral lines | 7 Pit privy | 10 Livestock pens | 14 Abandoned water well | | | |
| 2 Sewer lines | 5 Cess pool | 8 Sewage lagoon | 11 Fuel storage | 15 Oil well/Gas well | | | | |
| 3 Watertight sewer lines | 6 Seepage pit | 9 Feedyard | 12 Fertilizer storage | 16 Other (specify below) | | | | |
| Direction from well? DOWN SLOPE N | | | | How many feet? 85+ | | | | |
| FROM | TO | LITHOLOGIC LOG | | FROM | TO | PLUGGING INTERVALS | | |
| 0 | 3 | Earth | | | | | | |
| 3 | 6 | Red Clay | | | | | | |
| 6 | 25 | Broken lime | | | | | | |
| 25 | 65 | Hard lime | | | | | | |
| 65 | 85 | Grey Shale | | | | | | |
| 85 | 90 | Grey Shale | | | | | | |
| 90 | 98 | Red Bed | | | | | | |
| 98 | 120 | Shaly lime | | | | | | |

PLUGGED

AUG 31 1990

DIVISION OF
ENVIRONMENT

| |
|---|
| 7 CONTRACTOR'S OR LANDOWNER'S CERTIFICATION: This water well was (1) constructed, (2) reconstructed, or (3) plugged under my jurisdiction and was completed on (mo/day/year) 12/18/89 and this record is true to the best of my knowledge and belief. Kansas Water Well Contractor's License No. 493 This Water Well Record was completed on (mo/day/year) 12/18/89 by (signature) Jerry Reeder |
|---|