


2 WATER WELL OWNER: Wilma Ricketts Smith

3	LOCATE WELL'S LOCATION WITH AN "X" IN SECTION BOX:	4	DEPTH OF COMPLETED WELL: <u>UNKNOWN</u>	ELEVATION: <u>No CASING on Bore HOLE</u>
			Depth(s) Groundwater Encountered: <u>1</u>	<u>2</u>



Blank casing diameter 5 in. to 7 ft. Dia. 7 in. to 7 ft. Dia. 7 in. to 7 ft. Dia. 7 in. to 7 ft. Dia.

1 Steel	3 Stainless steel	5 Fiberglass	8 RMP (SR)	11 Other (specify) <i>NA</i>
2 Brass	4 Galvanized steel	6 Concrete tile	9 ABS	12 None used (open hole)

2 Louvered shutter 4 Key punched 7 Torch cut 10 Other (specify) *NA*

SCREEN-PERFORATED INTERVALS: From *NA* ft. to *NA* ft. From \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

		From		ft. to		ft., From		ft. to		ft.	
6	GROUT MATERIAL:	1 Neat cement	2 Cement grout	3 Bentonite	4 Other						

1 Septic tank	4 Lateral lines	7 Pit privy	11 Fuel storage	15 Oil well/Gas well
2 Sewer lines	5 Cess pool	8 Sewage lagoon	12 Fertilizer storage	16 Other (specify below)

FROM	TO	LITHOLOGIC LOG	FROM	TO	PLUGGING INTERVALS
10	3	ENVIROPLUG GROUT. 97F <sup>3</sup>			

[illegible]

Water Well Contractor's License No. 559 This Water Well Record was completed on (mo/day/yr) 10-19-93  
under the business name of Martin Water Well Drilling by (signature) [Signature]