WATER WELL PLUGGING RECORD Form WW	
1 LOCATION OF WATER WELL: Fraction County: Gove NW ¼NW¼ NW¼	Section Number Township Number Range Number Township Number Range Number 26 E 1/2 W
Street/Rural Address of Well Location; if unknown, distance &	Global Positioning Systems (GPS) information:
direction from nearest town or intersection: If at owner's address,	Latitude:(in decimal degrees)
check here Junction of Castle Rock Road & Kansas	Longitude:(in decimal degrees)
Hwy 212, Quinter, Kansas	Elevation:   Horizontal Datum:   WGS84,   NAD83,   NAD27
, , , , , , , , , , , , , , , , , , , ,	Collection Method:
2 WATER WELL OWNER: Grahams 66	GPS unit (Make/Model:
RR#, St. Address, Box #: Interstate 70 & Castle Rock Road	☐ Digital Map/Photo, ☐ Topographic Map, ☐ Land Survey
City, State ZIP Code: Quinter, KS 67752	Est. Accuracy: □ <3 m, □ 3-5 m, □ 5-15 m, □ > 15 m
3 MARK WELL'S LOCATION 4 DEPTH OF WELL 5	8.27 ft.
BOX: WELL'S STATIC WA	TER LEVEL 76.98 ft
N WELL WAS USED A	ς.
X '       <u> </u>	, – –
NW NE Domestic	Public Water Supply Dewatering
Irrigation _	Oil Field Water Supply Monitoring OZ-4
W E Feedlot Industrial	Domestic (Lawn & Garden) Air Conditioning  Injection Well Other
SW SE Industrial	Air Conditioning — Oulei
Was a chemical/bacteri	ological sample submitted to Department? Yes No 🛮
5 TYPE OF BLANK CASING USED:	
	thereless Other (Smarify heley)
Steel RMP (SR) Wrought F PVC ABS Asbestos-Cement C	oncrete Tile Other (Specify below)
Assestos-centent   Concrete Tile	
Blank casing diameter 2 in. Was casing pulled? Yes No If yes, how much 3' Casing height above or below land surface 36 in.	
6 GROUT PLUG MATERIAL: Neat cement Cement grout Bentonite Other	
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
Grout Plug Intervals: From <u>3</u> ft. to <u>88.27</u> ft., From ft. to ft., From ft. to ft.	
What is the nearest source of possible contamination:	
Septic tank Seepage pit  Fuel storage Other (specify below)	
Sewer lines Pit privy Fertilizer storage	
Watertight sewer lines   Sewage lagoon   Insecticide storage	
Lateral lines Feedyard Abandoned water well Direction from well?	
Cess pool Livestock pens Oil we	Il/Gas well How many feet?
FROM TO PLUGGING MATERIALS	FROM TO PLUGGING MATERIALS
0 3 Native soil	
3 88.27 Bentonite grout	
7 CONTRACTORS OR LANDOWNERS CERTIFICATION	Is. This yester well was alwayed under my indication and was
7 CONTRACTOR'S OR LANDOWNER'S CERTIFICATION: This water well was plugged under my jurisdiction and was completed on (mo/day/year) 4-25-16 and this record is true to the best of my knowledge and belief. Kansas Water	
Well Contractor's License No. 735  This Water Well Record was completed on (mo/day/year) 6-17-16  under the	
business name of MILCO Environmental Services, Inc.  by (signature) by (signature)	
Of Gignature of the Control of the C	
Send one white copy to Kansas Department of Health & Environment, Geology Section, 1000 SW Jackson Street, Ste. 420, Topeka, KS	
66612-1367. Send one copy to WATER WELL OWNER and retain one for your records.	
Visit us at <a href="http://www.kdheks.gov/waterwell/index.html">http://www.kdheks.gov/waterwell/index.html</a> Telephone 785-296-5524.	
KSA82a-1212 Revised 1/20/2015	
	un. 11.171

## MILCO Environmental Services, Inc.

June 21, 2016

320 West 4th Street Colby, KS 67701 Tel: 785-460-1956 Fax: 785-460-4220 www.milcoinc.com

Kansas Department of Health and Environment Bureau of Water - GWTS 1000 SW Jackson St, Ste 420 Topeka, KS 66612-1367

RE:

One Stop/Agro Petro/Travel Shoppe #3 - Oakley, Kansas KDHE Project Code U6-055-295/A6-055-40009/U6-055-11737 MILCO Project No. M250-P1-01

Graham's 66 Service - Quinter, Kansas KDHE Project Code: U6-032-00513 MILCO Project No. M269-P1-01

Holiday 66/I-C 66 KDHE Project Codes U6-026-00663/U6-026-14849 MILCO Project No. M273-P8-01

## Dear Sir or Madam:

Please find enclosed one (1) Water Well Plugging Record for the One Stop/Agro Petro/Travel Shoppe #3 site in Oakley. The well was abandoned by MILCO on May 20, 2016.

Please find enclosed fourteen (14) Water Well Plugging Records for the Holiday 66 site in Hays. The wells were abandoned by MILCO on June 1, 2016.

Please find enclosed twenty-five (25) Water Well Plugging Records for the Grahams 66 site in Quinter. The wells were abandoned by MILCO on April 25 and June 3, 2016.

If you need any additional information, please don't hesitate to contact us.

RECEIVED

JUN 2 3 2016

BUREAU OF WATER

Respectfully submitted,

MILCO Environmental Services, Inc.

Leah MacNeill

**Enclosures**