$\mathbf{W}_{A}$	ATER WEL	L PLU	<b>IGGING R</b>	RECORD	Form WV		KSA 82		ID NO.		
1	LOCATION O County: Ellis		ER WELL:		14 SE 14 NE	1/4 28	Number	T 1	Î3 S	Range Number 18	
	Street/Rural Address of Well Location: if unknown distance & Global Positioning Systems (GPS) information:										
	direction from nearest town or intersection: If at owner's address, check here 3701 Vine Hays Latitude:									(in decimal degrees)	
	check here 3701 Vine , Hays						Longitude:(in decimal degrees)				
							Elevation:  Horizontal Datum: WGS84, NAD83, NAD27  Collection Method:				
<del>                                     </del>								ka/Madalı			
2	WATER WE				Plaza		☐ GPS unit (Make/Model:				
	RR#, St. Address, Box #: PO Box 687 City, State ZIP Code: Hays, KS 67601										
	City, State Zi	P Code:	Hays, KS	6/601		Est. Accur	Est. Accuracy: $\square$ < 3 m, $\square$ 3-5 m, $\square$ 5-15 m, $\square$ > 15 m				
3	MARK WELL'S LOCATION 4 DEPTH OF WELL 9.00 ft.										
	BOX: WELL'S STATIC WATER LEVEL DRY ft										
	N WELL WAS USED AS:										
	NW NE NE Domestic Public Water Supply Dewatering										
w											
"	Industrial Air Conditioning Other Soil Vapor Extraction										
	SW SE SE SE SE SE SINGUISITAL AIR CONDITIONING SUB- SUB- SVE-1										
	Was a chemical/bacteriological sample submitted to Department? Yes No										
5	5 TYPE OF BLANK CASING USED:										
	Steel RMP (SR) Wrought Fiberglass Other (Specify below)  PVC ABS Concrete Tile										
1	Blank casing diameter 4 in. Was casing pulled? Yes No If yes, how much 3'										
	Casing height above or below land surface 36 in.										
6 GROUT PLUG MATERIAL: Neat cement Cement grout Bentonite Other											
	Grout Plug Intervals: From 3 ft. to 9.00 ft., From ft. to ft., From ft. to ft.										
	What is the nearest source of possible contamination:  Septic tank  Seepage pit  Fuel storage  Other (specify below)										
	Sewer lin		Se Pi	t privv		zer storage	□,	Outer (spec	ily below)		
	Watertigh	ht sewer	lines Se	ewage lagoor	Insect	icide storage	e				
	Lateral lin			eedyard		oned water					
	Cess pool	1	L Li	vestock pens	Oil we	ll/Gas well	Но	w many fe	et?		
	FROM	ТО	PLUG	GING MAT	ERIALS	FROM	ТО	P	LUGGING	MATERIALS	
	0 8"	'	Concrete							s approval, the well	
	8" 31		Native soil							left in place.	
	3 9		Bentonite he	ole plug							
7 CONTRACTOR'S OR LANDOWNER'S CERTIFICATION: This water well was plugged under my jurisdiction and was											
completed on (mo/day/year) 6-1-16 and this record is true to the best of my knowledge and belief. Kansas Water											
Well Contractor's License No. 735 This Water Well Record was completed on (mo/day/year) 6-20-16 under the											
business name of MILCO Environmental Services, Inc. by (signature) by (signature)											
Send one white copy to Kansas Department of Health & Environment, Geology Section, 1000 SW Jackson Street, Ste. 420, Topeka, KS											
66612-1367. Send one copy to WATER WELL OWNER and retain one for your records.											
					ks.gov/waterw						
	VOL00 1010 TO 1 14/00/004#										
	KSA82a-1212 Revised 1/20/2015										

\$ - \$\displaystyle{\beta}\_{1} :



Photos: Plugged SVE-1 - well vault left in place Holiday 66 site in Hays, Kansas MILCO Project No. M273-P8-01

## Environmental Services, Inc. 320 w. 4th Street Colby, KS 67701 Tel: 785-460-1956 Fax: 785-460-4220

## MILCO Environmental Services, Inc.

June 21, 2016

320 West 4th Street Colby, KS 67701 Tel: 785-460-1956 Fax: 785-460-4220 www.milcoinc.com

Kansas Department of Health and Environment Bureau of Water - GWTS 1000 SW Jackson St, Ste 420 Topeka, KS 66612-1367

RE:

One Stop/Agro Petro/Travel Shoppe #3 - Oakley, Kansas KDHE Project Code U6-055-295/A6-055-40009/U6-055-11737 MILCO Project No. M250-P1-01

Graham's 66 Service - Quinter, Kansas KDHE Project Code: U6-032-00513 MILCO Project No. M269-P1-01

Holiday 66/I-C 66 KDHE Project Codes U6-026-00663/U6-026-14849 MILCO Project No. M273-P8-01

## Dear Sir or Madam:

Please find enclosed one (1) Water Well Plugging Record for the One Stop/Agro Petro/Travel Shoppe #3 site in Oakley. The well was abandoned by MILCO on May 20, 2016.

Please find enclosed fourteen (14) Water Well Plugging Records for the Holiday 66 site in Hays. The wells were abandoned by MILCO on June 1, 2016.

Please find enclosed twenty-five (25) Water Well Plugging Records for the Grahams 66 site in Quinter. The wells were abandoned by MILCO on April 25 and June 3, 2016.

If you need any additional information, please don't hesitate to contact us.

RECEIVED

JUN 23 2016

BUREAU OF WATER

Respectfully submitted,

MILCO Environmental Services, Inc.

Leah MacNeill

**Enclosures**