
WATER WELL PLUGGING I	RECORD Form WW	C-5P KSA 82a-1212 ID NO.
1 LOCATION OF WATER WELL: County: Ellis	Fraction 1/4 NE 1/4 SE 1/4 NE 1/5	Section Number Township Number Range Number T 13 S T8 F W
Street/Rural Address of Well Location;		Global Positioning Systems (GPS) information:
direction from nearest town or intersection: If at owner's address, check here 3701 Vine, Hays		Latitude:(in decimal degrees) Longitude:(in decimal degrees)
		Elevation: Horizontal Datum: WGS84, NAD83, NAD27 Collection Method:
2 WATER WELL OWNER: Holid	day 66 Food Plaza	GPS unit (Make/Model:
RR#, St. Address, Box #: PO Box 687 City, State ZIP Code: Hays, KS 67601		Digital Map/Photo, Topographic Map, Land Survey
City, State ZIP Code: Hays, KS 67601 Est. Accuracy: \square <3 m, \square 3-5 m, \square 5-15 m, \square > 15 m		
3 MARK WELL'S LOCATION WITH AN "X" IN SECTION BOX:	4 DEPTH OF WELL 1	3.50 ft. TER LEVEL DRY ft
N N		
	WELL WAS USED AS	S:
W NE X E	Domestic Irrigation Feedlot Industrial	Public Water Supply Oil Field Water Supply Domestic (Lawn & Garden) Air Conditioning Dewatering Monitoring Injection Well Other Soil Vapor Extraction SVE-2
Was a chemical/bacteriological sample submitted to Department? Yes No		
5 TYPE OF BLANK CASING USED:		
Steel RMP (SR) Wrought Fiberglass Other (Specify below) PVC ABS Concrete Tile		
Blank casing diameter 4 in. Was casing pulled? Yes 1 No 1 If yes, how much 3' Casing height above or below land surface 36 in.		
6 GROUT PLUG MATERIAL: Neat cement Cement grout Bentonite Other		
Grout Plug Intervals: From <u>3</u> ft. to <u>13.50</u> ft., From ft. to ft., From ft. to ft.		
What is the nearest source of possible contamination: Septic tank Seepage pit Sewer lines Pit privy Fertilizer storage Watertight sewer lines Sewage lagoon Insecticide storage		
Watertight sewer lines	Sewage lagoon Insecti	cide storage
Lateral lines Feedyard Abandoned water well Direction from well?		
Cess pool Livestock pens Oil well/Gas well How many feet?		
FROM TO PLUC	GGING MATERIALS	FROM TO PLUGGING MATERIALS
0 8" Concrete	Jan Jan Halland Hou	* Per Pam Chaffee's approval, the well
8" 3 feet Native soil		vault and pad were left in place.
3 13.5 Bentonite h	nole plug	
7 CONTRACTOR'S OR LANDOWNER'S CERTIFICATION: This water well was plugged under my jurisdiction and was completed on (mo/day/year) 6-1-16 and this record is true to the best of my knowledge and belief. Kansas Water Well Contractor's License No. 735 . This Water Well Record was completed on (mo/day/year) 6-20-16 under the		
business name of MILCO Environmental Services, Inc. by (signature) by (signature)		
Send one white copy to Kansas Department of Health & Environment, Geology Section, 1000 SW Jackson Street, Ste. 420, Topeka, KS 66612-1367. Send one copy to WATER WELL OWNER and retain one for your records. Visit us at http://www.kdheks.gov/waterwell/index.html Telephone 785-296-5524.		
KSA82a-1212 Revised 1/20/2015		

ţ . ž



Photos: Plugged SVE-2 - well vault left in place Holiday 66 site in Hays, Kansas MILCO Project No. M273-P8-01

Environmental Services, Inc. 320 W. 4th Street
Colby, KS 67701
Tel: 785-460-1956
Fax: 785-460-4220

MILCO Environmental Services, Inc.

June 21, 2016

320 West 4th Street Colby, KS 67701 Tel: 785-460-1956 Fax: 785-460-4220 www.milcoinc.com

Kansas Department of Health and Environment Bureau of Water - GWTS 1000 SW Jackson St, Ste 420 Topeka, KS 66612-1367

RE:

One Stop/Agro Petro/Travel Shoppe #3 - Oakley, Kansas KDHE Project Code U6-055-295/A6-055-40009/U6-055-11737 MILCO Project No. M250-P1-01

Graham's 66 Service - Quinter, Kansas KDHE Project Code: U6-032-00513 MILCO Project No. M269-P1-01

Holiday 66/I-C 66 KDHE Project Codes U6-026-00663/U6-026-14849 MILCO Project No. M273-P8-01

Dear Sir or Madam:

Please find enclosed one (1) Water Well Plugging Record for the One Stop/Agro Petro/Travel Shoppe #3 site in Oakley. The well was abandoned by MILCO on May 20, 2016.

Please find enclosed fourteen (14) Water Well Plugging Records for the Holiday 66 site in Hays. The wells were abandoned by MILCO on June 1, 2016.

Please find enclosed twenty-five (25) Water Well Plugging Records for the Grahams 66 site in Quinter. The wells were abandoned by MILCO on April 25 and June 3, 2016.

If you need any additional information, please don't hesitate to contact us.

RECEIVED

JUN 23 2016

BUREAU OF WATER

Respectfully submitted,

MILCO Environmental Services, Inc.

Leah MacNeill

Enclosures