

WATER WELL RECORD

TEST PUMPING RESULTS

Date June 16/64OWNER Carl Stucky ADDRESS Moundridge, MoLOCATION OF FARM 3 1/2 mi N of Moundridge, 19-21-20 N 34 W

WELL

Depth 130 ft. Hard 118 ft pump & tail pipe holeCasing ft. Size 16 in. Gauge 10 Wt. W- Screen ft. Slot Description Placed from ft. to ft. & from ft to ft.Gravel Yds. Size

PUMPING RESULTS

SWL 42 FT.Pumped 50 min. through 8 in. discharge before beginning test.

RPM	GPM	DRAWDOWN	TIME	SWL
<u>1325</u>	<u>700</u>	<u>67 ft</u>	<u>12 20 PM</u>	
<u>1475</u>	<u>800</u>	<u>73.4 in</u>	<u>1 40</u>	
<u>1575</u>	<u>900</u>	<u>74.8 in</u>	<u>1 50</u>	
<u>1675</u>	<u>1000</u>	<u>78.6 in</u>	<u>1 55 PM</u>	<u>jump in</u>

Drop RPM back to 950 RPM took well - 76 in DC3 min to recover and stop pumping andThis well pump some fine sand although notCondition of water Brought sample in to be tested for salt. Only.

PUMPS

Make No. of Stages Pwls in.Impellers Shaft size Column Pipe Tailpipe Drop pipe MOTOR P.S. was down for 20 min to a fuel. Then started back up pump 1200 RPM for 3 min then went to an come back to 950 RPM recovered. normal pumping in 3 minR+B - D.D. Rosenkrantz
Company

over