

Best Available Copy

LOG OF TEST WELL
FOR
CATTLE FEEDERS, INC.

3 miles N
30th Plummer
3/4 E N S S
Cattle Feeder
Well, T

Located approximately 250 feet East of the Rock Island Railroad and 150 feet North of the trees, said trees being approximately 900 feet South of the Old Elevator building (Madora Grain).

Well was drilled May 11, 1970, finishing at 9:30 A.M. After leaving all day, water was raised to -9.5' at 6:00 P.M.

0' - 1'	Sandy Soil
1' - 2'	Sandy Soil
2' - 3'	Clay
3' - 4'	Sandy Clay
4' - 5'	Sandy Clay
5' - 6'	Sandy Clay
6' - 7'	Sandy Clay
7' - 8'	More Clay, Less Sand
8' - 9'	More Clay, Damp
9' - 10'	Clay and damp
10' - 11'	Clay and damp
11' - 12'	Clay, very damp
12' - 13'	Clay, wet
13' - 14'	Clay, very wet
14' - 15.5'	Solid Clay and bottom of water

The above Log of Test Well shown above is true and correct. Witness my signature, this the 12 day of May, 1970.

DARLING DRILLING COMPANY

Donald Darling