|                            |  |   | RECORD Form W  |   |  |   |  |  |  |  |  |
|----------------------------|--|---|--|---|--|---|--|--|--|--|--|
| County:                    |  | ER WELL:  | Fraction<br>¼ SW ¼ NE ¼ N  | E ¼ 20  | 1 Number   | T 24 S  | 14 <u>E</u> E                                      |  |  |  |  |
| direction f                | rom nearest to   | ,   | if unknown, distance & ion: If at owner's address,                                     | Latitude:<br>Longitud<br>Elevatior<br><u>Horizont</u>                                     | Global Positioning Systems (GPS) information:   Latitude: (in decimal degree   Longitude: (in decimal degree   Elevation: (in decimal degree   Horizontal Datum: WGS84, NAD83, NAI |   |  |  |  |  |  |
| RR#, St.                   | Address, Bo  | VNER: Eric V<br>ox #: 71 NW<br>: Macksville           | 80th Ave.  |   | Collection Method:GPS unit (Make/Model:Digital Map/Photo,Topographic Map,Land SurveyEst. Accuracy: $< 3 m$ , $3-5 m$ , $5-15 m$ , $> 15 m$   |   |  |  |  |  |  |
| WITH A<br>BOX:<br>NW       | S  |   |  | WATER LEV<br>OAS:<br>Oil Fiel<br>Domest<br>Air Cor  | EL 25<br>Water Supp<br>d Water Su<br>ic (Lawn &<br>ditioning   | ply Dew<br>upply Mon<br>& Garden) Injec   | atering<br>itoring<br>tion Well<br>r<br>Yes 🗌 No 🖌 |  |  |  |  |
| Casing h                   | C AB<br>sing diamete<br>eight above<br>PLUG MA                     | er <u>5</u> in.<br>or below land<br>TERIAL:           | Wrought<br>Asbestos-Cement<br>Was casing pulled? Yes<br>surface <u>3 ft. below</u> in. | ement grout   | If yes, he   | nite Other  |  |  |  |  |  |
| What is the Sept           | te nearest so<br>ic tank<br>er lines<br>ertight sewer<br>ral lines | urce of possib  | t privy Fer<br>ewage lagoon Inse<br>eedyard Aba  | rom<br>el storage<br>tilizer storage<br>ecticide storag<br>undoned water<br>well/Gas well | e —<br>well Di   | ft., From<br>Other (specify below)<br>rection from well? <u>W</u><br>ow many feet? <u>130</u> | I  |  |  |  |  |
| FROM                       | ТО   |   | GING MATERIALS   | FROM  | TO   |   | MATERIALS  |  |  |  |  |
| 78<br>25                   | 25<br>3  | gravel<br>bentonite                                   |  |   |  | Waters 1-20   |  |  |  |  |  |
| 3                          | 0  | top soil  |  |   |  | Sterling Drilling Con<br>P O Box 1006<br>Pratt, KS 67124                                      | mpany  |  |  |  |  |
| mpleted on<br>ell Contract | (mo/day/yea<br>or's License<br>of <u>Kelly's</u>                   | ar) <u>04/17/19</u><br>No. <u>186</u><br>Water Well S | . This Water We<br>ervice, Inc.  | record is true<br>Il Record was<br>by (s  | to the best<br>completed   | of my knowledge an  | nd belief. Kansas Wat<br>23/19 under th            |  |  |  |  |

| KS  | Α | 82 | a-  | 1 | 2 | 1 | 2 |
|-----|---|----|-----|---|---|---|---|
| 170 |   | 04 | í u |   | _ |   | _ |

**Revised 1/20/2015**