Aufescimatic MINTER-WILSON DRILLING CO. Vingerton Comments Comments Co.

INCORPORATED

HOLE TO THE CONTROL OF STREET AND THE STEEL HANDED TO BE

November 8, 1979

Pauline Alford Grant County

Location: SEk 4-30-36 From home place 1 mile East, & South 100' East, 100' North

Static Water Level - 142

0	1	Top Soil
1	20	Brown Clay
20	38	Brown Sandy Clay
38	66	Brown Clay
6 6	200	Gray Clay
200	224	Brown Gray Clay
224	269	Brown Sandy Clay
26 9	278	Brown Sandy Clay and sand streak
278	290	Fine to med. sand 15% Clay
290	304	Fine to med. sand & gravel 30% Clay
304	321	Brown Sandy Clay
321	352	Brown Sandy Clay Small Gravel streak
352	360	Fine to med. sand & gravel
360	407	Fine to med. sand & gravel 10% Clay (loose.
407	423	Brown Sandy Clay
423	437	Fine to med. sand & gravel 10% Clay
437	455	Brown Rock Clay streak 50 - 50% (loose)
455	470	Brown Rock
470	483	Brown Yellow Clay Brown Rock mixed no good
483	504	Brown Yellow Clay
504	509	Brown Yellow Clay Small loose streak of
		brown rock
50 9	587	Brown Gray Yellow Clay hard
587	590	Red Bed