

6 GROUT MATERIAL: 1 Neat cement 2 Cement grout X 3 Bentonite 4 Other
Grout intervals: From 54 ft. to 7 ft. From ft. to ft. From ft. to ft.
What is the nearest source of possible contamination:
1 Septic tank 4 Lateral lines 7 Pit privy 10 Livestock pens 14 Abandoned water well
2 Sewer lines 5 Cess pool 8 Sewage lagoon 11 Fuel storage 15 Oil well/Gas well
3 Watertight sewer lines 6 Seepage pit 9 Feedyard 12 Fertilizer storage X 16 Other (specify below)
..... HOUSE
Direction from well? west How many feet? 3

[illegible]

RECEIVED

~~AUG 03 1993~~

~~BUREAU OF WATER~~

7 CONTRACTOR'S OR LANDOWNER'S CERTIFICATION: This water well was ~~not~~ plugged under my jurisdiction and we completed on (mo/day/year) 7/30/93 and this record is true to the best of my knowledge and belief. Kansas Water Well Contractor's License No. _____ This Water Well Record was completed on (mo/day/yr) 7/30/93 under the business name of ADVANCE TERMITE & PEST CONTROL, INC. by (signature) Terry Savoy Terry Savoy

INSTRUCTIONS: Use typewriter or ball point pen, PLEASE PRESS FIRMLY and PRINT clearly. Please fill in blanks, underline or circle the correct answers. Send to three copies to Kansas Department of Health and Environment, Division of Environment, Environmental Geology Section, Topeka, KS 66620. Send one to WATER WELL OWNER and retain one for your records.