

| | |
|------------|-------------------------------------|
| Form | WWC5 |
| Contractor | Hydro Resources Mid Continent, Inc. |
| Well Owner | |
| Doc ID | 1304075 |

Litholgy

| From | To | LithologicLog |
|------|-----|---|
| 0 | 2 | top soil |
| 2 | 6 | fine sand |
| 6 | 34 | brown sandy clay |
| 34 | 46 | fine sand |
| 46 | 71 | brown sandy clay |
| 71 | 84 | fine sand cemented in places |
| 84 | 93 | brown clay |
| 93 | 104 | fine sand |
| 104 | 106 | sand fine to med coarse |
| 106 | 148 | brown sandy clay |
| 148 | 181 | sand fine to med w/ couple clay stringers |
| 181 | 192 | sand fine to med w/ couple clay stringers |
| 192 | 204 | brown sandy clay w/ few sand strips |
| 204 | 218 | sand fine to med coarse |
| 218 | 240 | sand fine to med w/ some clay stringers |
| 240 | 258 | fine sand w/ some clay ledges |
| 258 | 303 | cemented sand w/ few clay ledges |
| 303 | 450 | fine sand w/ some clay stringers |
| 450 | 498 | fine sand w/ some clay stringers |

| | |
|------------|-------------------------------------|
| Form | WWC5 |
| Contractor | Hydro Resources Mid Continent, Inc. |
| Well Owner | |
| Doc ID | 1304075 |

Litholgy

| From | To | LithologicLog |
|------|-----|----------------------------------|
| 498 | 671 | fine sand w/ few clay stringers |
| 671 | 700 | fine sand w/ some clay stringers |
| 700 | 740 | fine sand |
| 740 | 760 | red bed |