W	ATER WELL PLUGGING I	RECORD Form WW	C-5P KS	4 82a-1212 I	D NO.	144-Q	
1	LOCATION OF WATER WELL: County: Phillips	Fraction 1/4 SE 1/4 SE 1/4 SW	Section Numb	Т 3	S	Range Number 16	
	Street/Rural Address of Well Location; if unknown, distance & Global Positioning Systems (GPS) information:						
		ection from nearest town or intersection: If at owner's address, Latitude: 39.756642 (in decimal degrees)					
	check here 819 Frontage Road, Agra Elevation:						
			Horizontal Datus Collection Meth		, <u> </u>	NAD83, 🗌 NAD27	
2	2 WATER WELL OWNER: Farmer's National Bank						
_	RR#, St. Address, Box #: PO Bo	☐ Digital Ma	Digital Map/Photo, Topographic Map, Land Survey				
	City, State ZIP Code: Phillipsburg, KS 67661 Est. Accuracy: \square <3 m, \square 3-5 m, \square 5-15 m, \square > 15 m						
3	MARK WELL'S LOCATION 4 DEPTH OF WELL 46.50 ft.						
	WITH AN "X" IN SECTION						
	N I						
	WELL WAS USED AS:						
	NW NE Domestic Public Water Supply Dewatering						
	W Irrigation Oil Field Water Supply Monitoring IW-8 Feedlot Domestic (Lawn & Garden) Monitoring IW-8 Injection Well						
W	Industrial Air Conditioning Other						
	SW SE SE MINIMUSTRAL STATE CONDITIONING STATE CONTINUOUS						
	Was a chemical/bacteriological sample submitted to Department? Yes No						
5 TYPE OF BLANK CASING USED:							
Steel RMP (SR) Wrought Fiberglass Other (Specify below)							
***************************************	PVC ABS Asbestos-Cement Concrete Tile						
Blank casing diameter 1 in. Was casing pulled? Yes 🗹 No 🗌 If yes, how much approx 2'							
	Casing height above or below land surface 24 in.						
6 GROUT PLUG MATERIAL: Neat cement Cement grout Bentonite Other							
Grout Plug Intervals: From 2 ft. to 46.50 ft., From ft. to ft., From ft. to ft.							
What is the nearest source of possible contamination:							
	Septic tank Seepage pit Fuel storage Other (specify below)						
Sewer lines Pit privy Fertilizer storage							
Watertight sewer lines Sewage lagoon Insecticide storage Lateral lines Feedyard Abandoned water well Direction from well?							
Cess pool Livestock pens Oil well/Gas well How many feet?							
energen en e	FROM TO PLUC	GGING MATERIALS	EDOM TO) BI 1	IGGING A	MATERIALS	
and the same same same same same same same sam	FROM TO PLUG	JOINO MATERIALS	FROM TO	PLU	DAILDO	MATERIALS	
	2 46.50 Bentonite C	Prout			***************************************		
***************************************	2 46.50 Demonite C						
-					***************************************		
				Shamrock S	Service si	te U6-074-00224	
200 COOK OF CO				Onamook	2014100 31	10 00 07 4 00224	

7 CONTRACTOR'S OR LANDOWNER'S CERTIFICATION: This water well was plugged under my jurisdiction and was							
completed on (mo/day/year) 10/18/18 and this record is true to the best of my knowledge and belief. Kansas Water							
Well Contractor's License No. 735 . This Water Well Record was completed on (mo/day/year) 10/24/18 under the							
business name of MILCO Environmental Services, Inc. by (signature) by (signature)							
Send one white copy to Kansas Department of Health & Environment, Geology Section, 1000 SW Jackson Street, Ste. 420, Topeka, KS							
66612-1367. Send one copy to WATER WELL OWNER and retain one for your records.							
		p://www.kdheks.gov/waterw					
KSA82a-1212 Revised 1/20/2015							

IW-8



October 26, 2018

320 West 4th Street Colby, KS 67701 Tel: 785-460-1956 Fax: 785-460-4220 www.milcoinc.com

Kansas Department of Health and Environment Bureau of Water - GWTS 1000 SW Jackson St, Ste 420 Topeka, KS 66612-1367

RE:

Shamrock Services

819 Frontage Road, Agra, KS

KDHE Project Code: U6-074-00224 MILCO Project Number: M287-P1-14

Dear Sir or Madam:

Please find enclosed sixteen (16) Water Well Plugging Records WWC-5PS for the Former Shamrock Services site in Agra, KS. The wells were abandoned by MILCO Environmental Services on October 18, 2018.

If you need any additional information, please don't hesitate to contact us.

Respectfully submitted,

MILCO Environmental Services, Inc.

arty of Wheelbarge

Kathy Wheelbarger

KJW/

RECEIVED

Enclosures

OCT **3 0** 2018

BUREAU OF WATER