W	ATER WELL PLUGGING I	RECORD Form WW	/C-5P	KSA 82a-1212	ID NO.	IW-15	
1	LOCATION OF WATER WELL:		Section N		hip Number	Range Number	
-	County: Phillips	4 SE 4 SE 4 SW				16   E   W	
	Street/Rural Address of Well Location; if unknown, distance & direction from nearest town or intersection: If at owner's address,  direction from nearest town or intersection: If at owner's address,						
	check here 819 Frontage Road, Agra  Longitude: 99.115697					(in decimal degrees)	
					7004 D	NAD83, NAD27	
PACE CONTRACTOR			Horizontal D Collection M		1584,	NAD83,   NAD27	
-	WATER WELL OWNER: Far	marie National Bank		init (Make/Model:			
2	RR#, St. Address, Box #: POBo		Digital	il Map/Photo,	Topographic M	lap, 🔲 Land Survey	
				_	_	5-15 m,	
3	MARK WELL'S LOCATION 4 DEPTH OF WELL 46.70 ft. WITH AN "X" IN SECTION						
BOX: WELL'S STATIC WATER LEVEL 36.75 ft							
	N WELL WAS USED AS:						
	NW NE	Domestic Irrigation	Public Wat	ter Supply Vater Supply	Dewat Monito	oring IW-15	
W	E	Feedlot		(Lawn & Garden)		on Well	
	sw se Industrial Air Conditioning Other						
ender execute money	X	was a chemical/bacter	ological sampl	ie submitted to 120	parmient; i		
5 TYPE OF BLANK CASING USED:							
	Steel RMP (SR) Wrought Fiberglass Other (Specify below)  PVC ABS Concrete Tile						
	Blank casing diameter1 in. Was easing pulled? Yes No If yes, how much _approx 2'						
Casing height above or below land surface 24 in.							
6 GROUT PLUG MATERIAL: Neat cement Cement grout Bentonite Other							
Grout Plug Intervals: From 2 A to 46.70 A F A to 46.70 A							
Grout Plug Intervals: From 2 ft. to 46.70 ft., From ft. to ft., From ft. to ft.							
	What is the nearest source of possible contamination:						
	Sceptic tank Scepage pit Fuel storage Other (specify below)						
	Sewer lines Pit privy Fertilizer storage Watertight sewer lines Sewage lagoon Insecticide storage						
	Lateral lines   Feedyard   Abandoned water well   Direction from well?						
	Cess pool Livestock pens Oil well/Gas well How many feet?						
	FROM TO PLUC	GING MATERIALS	EDOM	то	DI LICCINC	MATERIALS	
	0 2 Asphalt	JUNU WATEKIALS	FROM	10	FLUGUING !	MATERIALS	
		Srout					
	2 46.70 Bentonite C			100	A		
		A. HHI. A.		Shamre	ock Service s	ite U6-074-00224	
				Jan			
7 (	7 CONTRACTOR'S OR LANDOWNER'S CERTIFICATION: This water well was plugged under my jurisdiction and was						
completed on (mo/day/year) 10/18/18 and this record is true to the best of my knowledge and belief. Kansas Water							
Well Contractor's License No. 735 . This Water Well Record was completed on (mo/day/year) 10/24/18 under the							
business name of MILCO Environmental Services, Inc. by (signature) by (signature)							
Send one white copy to Kansas Department of Health & Environment, Geology Section, 1000 SW Jackson Street, Ste. 420, Topeka, KS							
66612-1367. Send one copy to WATER WELL OWNER and retain one for your records.							
Visit us at http://www.kdheks.gov/waterwell/index.html Telephone 785-296-5524.							
		KSA	82a-1212			Revised 1/20/2015	

IW-15



October 26, 2018

320 West 4th Street Colby, KS 67701 Tel: 785-460-1956 Fax: 785-460-4220 www.milcoinc.com

Kansas Department of Health and Environment Bureau of Water - GWTS 1000 SW Jackson St, Ste 420 Topeka, KS 66612-1367

RE:

Shamrock Services

819 Frontage Road, Agra, KS

KDHE Project Code: U6-074-00224 MILCO Project Number: M287-P1-14

Dear Sir or Madam:

Please find enclosed sixteen (16) Water Well Plugging Records WWC-5PS for the Former Shamrock Services site in Agra, KS. The wells were abandoned by MILCO Environmental Services on October 18, 2018.

If you need any additional information, please don't hesitate to contact us.

Respectfully submitted,

MILCO Environmental Services, Inc.

arty of Wheelbarge

Kathy Wheelbarger

KJW/

RECEIVED

**Enclosures** 

OCT **3 0** 2018

BUREAU OF WATER