


Dual Compensated Porosity Log


DIGITAL LOG
(785) 625-3858

<<< Fold Here >>>
All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.
Comments
Thank you for using Log-Tech, Inc. (785) 625-3858 Riga Exit, 11 1/4 North, West Into at Tank Batteries

Database File: c:\warrior\data\murfin_zeigda unit no. 1-4\murfin_zeigdaunit_4hd.db
Dataset Pathname: dil\murfstck
Presentation Format: cdl
Dataset Creation: Fri May 21 13:12:48 2010
Charted by: Denth in Feet scaled 1:600

Charted by: Depth in Feet scaled 1:600					
0	Gamma Ray	150	30	Compensated Density	-10
6	Caliper (GAPI)	16	2	Bulk Density	3
			15000	Line Tension	0
			-0.25 Correction 0.25		
			LSPD		





Database File: c:\warrior\data\murfin_zeigda unit no. 1-4\murfin_zeigdaunit_4hd.db
 Dataset Pathname: dil/murfstck
 Presentation Format: cndlspec
 Dataset Creation: Fri May 21 13:12:48 2010
 Charted by: Depth in Feet scaled 1:240

