



**COMPLETION
& PRODUCTION
SERVICES CO.**

DUAL RECEIVER CEMENT BOND LOG

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments

THANK YOU FOR USING NABORS COMPLETION & PRODUCTION SERVICES
HAYS, KANSAS (785) 628-6395

DIRECTIONS




PROTECTION, KS. 5 OR 6 W ON HWY 160 TO RD. 30 - 4 N TO CATTLE GUARD - 3/4 W - S INTO


Database File: 10430grb.db
Dataset Pathname: pass2.1
Presentation Format: dcb102
Dataset Creation: Sun Dec 30 12:54:00 2012
Charted by: Depth in Feet scaled 1:240

Charted by: Depth in Feet scaled 1:2.15		
0	Gamma Ray (GAPI)	150
210	5' Travel Time (usec)	1000

0	3' Amplitude (mV)	100
9	CCL	-1
0	Amplified Amplitude (mV)	20

200	5FT VDL	1000
-----	---------	------







5100




5150


5200

5250

5300










5550

5600

5650

5700







5750


5800

5850

5900

5950










6000


6050

6100



6150







6450



200 5FT VDL 1000