

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy, correctness or completeness of any interpretation, and we shall not, except in the case of gross or wilful negligence on our part, be liable or responsible for any loss, cost, damages or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions as set out in our current price schedule.

Comments

South of Medicine Lodge on 281 2.2 mi.
W on Pleasant Valley Rd. Stay on main rd.
when rd. curves S go across 2 cattle guards and stay on main rd. to top of hill across from Griffin tank battery

ABAN Cavulated for 5.5" Casing.

Thanks for using The Perforators LLC, Hays, KS. (785)621-4804.

Main Pass

Database File: rgadenscreen6.db
Dataset Pathname: pass1
Presentation Format: dual
Dataset Creation: Sat Aug 18 17:58:38 2012 by Log Open Excel 109527
Charted by: Depth in Feet scaled 1:240

GR (GAPI)	150	MPDP (pu)	0
R (OHMM)	0.2	DPDP (pu)	30
BCREC (in)	16	TPDP (pu)	30
		RHOC (g/cc)	3
		3000	1.7500 lbs

Time1 (hr)