



<<< Fold Here >>>
All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.
Comments
E of Medicine Lodge cross into Harper county and take 140th S to hyw 2, go E on hyw 2 to 80th rd.,S on 80th 3 mi., W into.
Thanks for using The Perforators LLC Hays, KS. (785-621-4604)




Database File: cgsrivner#1bscbl.db
Dataset Pathname: pass2
Presentation Format: cblsec
Dataset Creation: Tue Nov 01 13:16:46 2011 by Log Open-Cased 100827
Charted by: Depth in Feet scaled 1:240

0	GR (GAPI)	150
150	GR (GAPI)	300
450	TT3 (usec)	250

18	CCL	-2
0	AMP3 (mV)	100

200 VDL 1200






3750


3800

3850

3900










4150


4200

4250

4300









4600

4650

4700

4750






4800



4850

4900

4950

5000







Repeat Pass

Database File: cgsrivner#1bscbl.db
 Dataset Pathname: pass1
 Presentation Format: cblsec
 Dataset Creation: Tue Nov 01 13:09:48 2011 by Log Open-Cased 100827
 Charted by: Depth in Feet scaled 1:240

0	GR (GAPI)	150
150	GR (GAPI)	300
450	TT3 (usec)	250

18	CCL	-2	200	VDL	1200
0	AMP3 (mV)	100			





Calibration Report		
Database File:	cgsrivner#1bscbl.db	
Dataset Pathname:	pass1	
Dataset Creation:	Tue Nov 01 13:09:48 2011 by Log Open-Cased 100827	
Gamma Ray Calibration Report		
Serial Number:	080611	
Tool Model:	P2	
Performed:	Fri Jul 29 15:37:45 2011	
Calibrator Value:	1.0	GAPI
Background Reading:	0.0	cps
Calibrator Reading:	1.0	cps
Sensitivity:	1.1000	GAPI/cps
Segmented Cement Bond Log Calibration Report		
Serial Number:	080321	
Tool Model:	ProbeRadial	
Calibration Casing Diameter:	5.500	in
Calibration Depth:	101.895	ft
Master Calibration, performed Tue Aug 16 10:26:07 2011:		
Raw (v)	Calibrated (mv)	Results

