API # 15-111-20,450

MIDWEST SURVEYS
LOGGING & PERFORATING SERVICES
P.O. BOX 1342 - 1000 E. 7th
EL DORADO, KANSAS 67042
316-321-9783 - 316-321-7126

File No.

Company: Trimble & Mecklenby Oil, LLC.
Well: Brookfield No.- 1
Field:
County: Lyon State: Kansas
Location: 1000' FSL & 2000' FEL
SW SW SW
Sec. 33 Twp. 20s Rge. 10e
Elev.: KB: 1100 DF: GL: Permanent Datum: Ground Level
Date: 12-10-20
Run No.: 1
Depth Driller: 2500
Depth Logger: 2500
Bottom Log Interval: 2500
Top Log Interval: 70
Casing Driller: 8 5/8 @ 20
Casing Logger: 20
Bit Size: 7 7/8
Type Fluid in Hole: Water
Dens. / Visc.: N/A
pH / Fluid Loss: N/A
Source of Sample: Flowline
Rm @ Meas. Temp.: N/A
Rmf @ Meas. Temp.: N/A
Rmc @ Meas. Temp.: N/A
Source: Rmf / Rmc: N/A
Rm @ BHT: N/A
Time Since Circ.: 1 hr
Max. Rec. Temp.: 70
Equipment Location: EL DORADO
Recorded By: Jason Thomas
Witnessed By: Mr. Gulick

GAMMA RAY / NEUTRON / CCL

Comments

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not be liable or responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments

Drilling Contractor :
Gulick Drilling Company, Inc.

Database File: ratfile1.db
Dataset Pathname: pass1
Presentation Format: gr-ncl
Dataset Creation: Fri Dec 25 12:10:28 2020 by Log SCAN 1111N
Charted by: Depth in Feet scaled 1:240