

>>> Field Data <<<

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments

THANK YOU FOR USING
PERF-TECH WIRELINE SERVICES, INC.
785-628-3969

DIRECTIONS: BAZINE, KS.
HWY 96, EE rd,1/2 NORTH ,
NW into

Perf-Tech Wireline Services

MAIN PASS

Database File: den281206.db
Dataset Pathname: pass3
Presentation Format: 3x3
Dataset Creation: Fri Dec 28 14:46:08 2012 by Log SCH 111116
Charted by: Depth in Feet scaled 1:240

0 Gamma Ray (GAPI) 150 | 0 3 AMPLITUDE (mV) 100 200 | 0 Variable Density 1100
575 3 TRAVEL TIME (usec) 235
0 Collar Locator -1

3300
3350
3400
3450
3500
3550
3600
3650
3700
3750
3800
3850
3900
3950
4000
4050
4100
4150
4200

Top of Cement

Casing Collar
3 TRAVEL TIME
3 AMPLITUDE
Gamma Ray
LOGGED TO 4223

0 Gamma Ray (GAPI) 150 | 0 3 AMPLITUDE (mV) 100 200 | 0 Variable Density 1100
575 3 TRAVEL TIME (usec) 235
0 Collar Locator -1

Perf-Tech Wireline Services

REPEAT SECTION

Database File: den281206.db
Dataset Pathname: pass2
Presentation Format: 3x3
Dataset Creation: Fri Dec 28 14:42:19 2012 by Log SCH 111116
Charted by: Depth in Feet scaled 1:240

0 Gamma Ray (GAPI) 150 | 0 3 AMPLITUDE (mV) 100 200 | 0 Variable Density 1100
575 3 TRAVEL TIME (usec) 235
0 Collar Locator -1

4100
4150
4200

0 Gamma Ray (GAPI) 150 | 0 3 AMPLITUDE (mV) 100 200 | 0 Variable Density 1100
575 3 TRAVEL TIME (usec) 235
0 Collar Locator -1