



Pioneer Energy Services

Borehole Compensated Sonic Log

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.


Comments



Thank you for using Log-Tech, Inc.
(785) 625-3858



Olmitz, KS:
Hwy 4: E to 70 Rd., 1S, 1/2W, N into



Database File: rjm_hd.db
Dataset Pathname: dil/rjmmain
Presentation Format: sonic
Dataset Creation: Mon Sep 03 01:00:51 2012
Charted by: Depth in Feet scaled 1:240



0	Gamma Ray	150	Sonic Int	140	Delta Time (usec/ft)	40
150	Gamma Ray	300	5	0	Sonic Porosity	-10
6	dCAL (GAPI)	16		30	LTEN (lb)	0
				15000		
						LSPD











































3500

3550

3600

Sonic Int
5 0



-31

-31

-30

0	Gamma Ray	150
150	Gamma Ray	300
6	dCAL (GAPI)	16

140	Delta Time (usec/ft)	40
30	Sonic Porosity	-10
15000	LTEN (lb)	0

LSPD