



Pioneer Energy Services

Dual Compensated Porosity Log

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments


Thank you for using Log-Tech, Inc.
(785) 625-3858


Sharon, 3 South on Tri-City Blacktop, 1/4 West, North Into


Database File: chieftain_lichlyter_2hd.db
Dataset Pathname: dil/chiefstck
Presentation Format: cdl
Dataset Creation: Fri Aug 31 01:25:08 2012
Charted by: Depth in Feet scaled 1:600


0	Gamma Ray	150
6	Caliper (GAPI)	16

30	Compensated Density	-10
2	Bulk Density	3
15000	Line Tension	0
-0.25	Correction	0.25
LSPD		









Database File: chieftain_lichlyter_2hd.db
Dataset Pathname: dil/chiefstck
Presentation Format: cndlspec
Dataset Creation: Fri Aug 31 01:25:08 2012
Charted by: Depth in Feet scaled 1:240

